

Photograph 1 of 6
Detail of the east side of the corner entrance, showing decorative brick work, stuccoed belt cornice and wood sash windows. Looking west.

Ted R. Schneider Photo, 1985 PO Box 12026 Portland, OR 97212



Photograph 2 of 6 Close up of corner entrance and relationship of the steel I-beam ground floor store fronts and the upper floor brick. Looking south.

PO Box 12026

Portland, OR 97212

Ted R. Schneider Photo, 1985



Photograph 3 of 6 Looking south at the north (Everett Street) and east (3rd Avenue) elevations, showing the two story air rights development mid-block on 3rd Avenue, and the window pattern and general building compatibility with remainder of block.

> Ted R. Schneider Photo, 1985 PO Box 12026 Portland, OR 97212



Photograph 4 of 6 The east elevation on 3rd Avenue, looking west, showing the two story air rights development; articulated parapet wall, stone coping and decorative brick work, stringcourse.

Ted R. Schneidder Photo, 1985 PO Box 12026 Portland, OR 97212



Photograph 5 of 6 View of the 3rd Avenue storefront, showing the structural I-beam columns, with the display window infill; plywood and brick veneer covering original storefront material still existing.

Ted R. Schneider Photo, 1985 PO Box 12026 Portland, OR 97212



Photograph 6 of 6
The north elevation (Everett Street) looking south, showing the articulated parapet wall, original entrances including the exterior basement entrance location at mid point of the elevation.

Ted R. Schneider Photo, 1985 PO BOx 12026 Portland, OR 97212