of SOUTH NATIONAL BANK DAKQTA RS

First National Bank Building of Vermillion Vermillion, SD M. Betz November 1985 State Historical Preservation Center Front Facade, Looking South Photograph #1 of Seven

NATIONAL BANK OF SOUTH DAKOTA


First National Bank Building of Vermillion Vermillion, SD M. Betz November 1985 State Historical Preservation Center Front and Side Facades, Looking Southeast Photograph #2 of Seven



First National Bank Building of Vermillion Vermillion, SD M. Betz November 1985 State Historical Preservation Center Side Facade, Looking Northeast Photograph #3 of Seven



First National Bank Building of Vermillion Vermillion, SD M. Betz November 1985 State Historical Preservation Center Rear Facade, Looking North Photograph #4 of Seven



First National Bank Building of Vermillion Vermillion, SD M. Betz November 1985 State Historical Preservation Center Front Door Photograph #5 of Seven



First National Bank Building of Vermillion Vermillion, SD M. Betz Novemeber 1985 State Historical Preservation Center Interior, 1st Floor Photograph #6 of Seven



First National Bank Building of Vermillion Vermillion, SD M. Betz November 1985 State Historical Preservation Center Lighting Fixture Photograph #7 of Seven