Iowa Site Inventory Office of Historic Preservation Iowa State Historical Department East 12th & Grand Avenue Des Moines. Iowa 50319

Site Number	111
District Name	
Man Reference #	111

## Identification

1

5

	Site Name MCCoy Polygonal	Barn						
1.	Site NameHerburn wic	Datn		110		<u> </u>		
		e/Town/City Hepburn vic. Township Valley			County_Page			
		70 N			36 W	16	NIT	<u> </u>
4.	Legal LocationUrban: si	Ubdivision			block	D parcel		subparcel
	Rurai: to	ownship			range	section		¼ section of ¼ section
_	15	332	630	/ 525	5 490 .	lace	than	000 2000
	UTM Location: zone <u>15</u> eastir		050_northi	ng <del>-</del> , <u>5</u> 25	, 470; Acreage	1633	Liiaii	one acte
6.	Owner(s) Name Malcom McCoy	#1	17171		Tot	a	5086	
7.	Owner(s) Address R. R.	#	 	ity)	<u></u>	late)		(Zip)
							<b>~</b> n	•
8.	Use: Present Hog barn			Original	Jares p		211	
~								
D	escription				-			
	Date of Construction 1914	Archi	itect/Builder					
10.	Building Type:	strial		🗆 other	r institutional		🗌 religi	ous
		ational		🗌 publi			📕 agric	
					. –			
11.	Exterior Walls: Clapboard stone and stone and stone shiplap		board and ba	tten 📋 shi	ngles 📋 stucco	1		
12.	Structural System: wood frame with into masonry load-bearing walls iron fra	terlocking	joints <b>M</b> wood	d frame with	n light members	(balloon fr.	ame)	
			steel frame wit	in curtain wa		eu concrete		
	other	······						
		· - · ·						
	Condition: excellent good fa							
14.	Integrity: In original site In moved—if Notes on alterations, additions (with dates	so, when? s and archi	tect if known	and any ot	her notable featu	ires of buil	ding and	site:
	Holes on allerations, additions (with date			, and any or			angano	site.
	See reverse side.							
15.	Related Outbuildings and Property: 🗌 b	arn 🗮 ot	her farm struc	tures 🗌 ca	arriage house	]garage [	] privy	
	other							
16.	Is the building endangered? 📕 no 🗌 ye	es—if so, w	vhy?					
								· · ·
17.	Surroundings of the building: Open la			attered out	buildings 📋 de	nsely built-	up⊔c	ommercial
	🗌 industrial 🔲 residential 📋 other							
	8=.16 W	TGOMERY C	1 00					
18.	Map LIGHTA POWER (71) TO			9. Photo	<u> 31 Frame 19</u>			1
। .चन्नः:-	- H			Roll	J Frame J	View _	<b></b>	
įΩ.			5 C					
14-			5	VBD:	A circle	501 1-	diam	eter, based
4		· • •		VDD:	A circle			f the barn,
Te/								d to west.
	79 10 10 11	N 12	41		excludes	accacite	u sne	a to west.
-			#111					
Ŀ		. 1 1	T-70N					
	19	24						
	- MEPBURN	•	E1					
		-						
	30 • 12 - 20 - 27 - 26	•						
						MAY 2	7 1000	
						MAY 2	1 1900	ן נ
• •	31	1 26	X					I
1	- 1 37 I 33 [7] 34 - 35 I							
<b>v</b> +								

## Significance

 $\Theta$  (Indicate sources of information for all statements)

20. Architectural significance

a. Key structure/individually may qualify for the National Register

b. Contributing structure

C. Not eligible/intrusion

N/A

Continuation of 14. Integrity.

Circular interior. 6 - sided barn with 30' diameter. 6 - sided Monitor with 12 windows.

Common Variation; Monitor type. Theme(5) \_\_\_\_\_ Special Function; Farm Sale type.

21. Historical Significance

a. Key structure/individually may qualify for the National Register

□ b. Contributing structure

C. Not eligible/intrusion

One of five round barns with a multi-windowed monitor known to have been built on an lowa farm, and one of only two which remain in good condition. Monitor round barns are specifically characterized by a large multi-windowed monitor, of much greater proportion than standard cupolas, which is designed to provide natural light to the barn's interior. Several of these barns were built in lowa along the lines of a circular hoghouse in McLean County, Illinois which was featured in the February 26, 1920 issue of <u>Breeder's Gazette</u>. The McCoy Round Barn was originally built as a hog sale barn, which would explain the owner's concern for good light.

22. Sources (for primary and secondary sources, give complete facts of publication: author, title, place of publication, date, etc.):

Malcolm McCoy, Villisca, IA 50864

Soike, Lowell J. <u>Without Right Angles</u>. Des Moines, Iowa: Iowa State Historical Department, Office of Historic Preservation, 1983.

Prepared by	· •	_Date
Address		Telephone
Organization		

<ol> <li>Office Information Sources on this Property         County Resource File     </li> </ol>	Review and Compliance Project:	
Windshield Survey	Other	
🗌 National Register	Other	
Grants-In-Aid:	Other	
Determination of Eligibility		
	3. Photo Images	
2. Subject Traces		
a		
b		
(		
d		
e		