| | | Site | # | CL-3 |
|------|---|------|---|-------|
| Page | 1 | of _ | 2 | Pages |

J

KENTUCKY HISTORIC RESOURCES INVENTORY

| ${1.}$ | Name of Site: | 16. Date: | | |
|-------------|--|--|--|--|
| Τ. | Henry Ogburn House | Ca. 1845 [3] | | |
| | | Ca. 1045 [5] | | |
| 2. | Prehistoric Site Building X Object | 17 (4-1- | | |
| <u> </u> | Historic Site Structure Other | 17. Style: | | |
| 3. | Location: | Greek Revival [C] | | |
| | 1400 feet south of U.S. 42; | 10 11 1 | | |
| | ADD/County: at Carrallon | 18. Architect/Builder: | | |
| 4. | | 10 No of Charles 2 1 1 1 1 | | |
| 5. | Carroll [021] Original Owner: | 19. No. of Stories: 2 plus basement [C] | | |
| ٠. | • | 20. Original Floor Plan: | | |
| 6. | Henry Ogburn Other Names: | Central Passage? [I] 21. Single Pile X Double Pile N.A. | | |
| 0. | other names: | 21. Single Pile X Double Pile N.A. 22. Roof Form & Original Material: | | |
| 7. | Owners Name: | Flat | | |
| / • | John Tilley | 23. Structural Material: | | |
| 8. | Owners Address: | Stone [B] | | |
| ٠, | Quinn Acres | 24. Exterior Finish: | | |
| | Carrollton, KY 41008 | Stone [S] | | |
| 9. | Evaluation: | 25. Foundation Material: | | |
| <i>,</i> | Meets Nat. Reg. [¢] | Stone [A] | | |
| 10. | Status & Date: | 26. Major Alterations: | | |
| | Nat.Landmark KY Survey X-Sp.1981 | Moved Wall Treat. | | |
| | Nat.Register Local Landmark | Additions None | | |
| المجر رياح | Landmark Cert. HABS/HAER | 27. Outbuildings: | | |
| 11. | N.R.Group | Log quarters [1] | | |
| 7 | District Name [] | 28. Original Use: | | |
| | Mult.Resource Area | Residence [A] | | |
| | Thematic Name Early Stone Bldgs. [] | 29. Present Use: | | |
| 12. | Historical Theme: | Residence | | |
| | Primary: Architecture [C] | 30. Condition: | | |
| | Secondary: [] | Excellent [A] | | |
| | Other: | 31. Endangered Yes | | |
| 13. | Statement of Significance: | No X | | |
| | | 31. Attach Photos | | |
| | One of two early stone houses in county. | Roll: 28 Photo Nos: 21-28 | | |
| | Uncommon in Greek Revival period in | | | |
| | Kentucky. In excellent condition, | shede also | | |
| | • | | | |
| | | | | |
| | | | | |
| 14. | History: | | | |
| | | | | |

of Port William

Henry Ogburn was first resident minister

^{15.} Source of Historical Information: 1981 Survey Form

^{33.} Prepared by: Carolyn Murray Wooley
34. Organization: Kentucky Heritage Council
35. Date: June 1984

KENTUCKY HISTORIC RESOURCES INVENTORY

| 36. UTM Point of Primary Building: | 37, USGS Quadrant: | 38. G.I.S. Mod. [|
|--|-----------------------|-----------------------------|
| 16-662410-4283970 | Carrollton | 39. Coordinate Accuracy [|
| 40. UTM Points of Boundary: A. 16-662575,4283995 C. | 16.662130. 284080 | E. 16.662330.4284080 |
| B. 16.662320-4283800 D. | | F. 16.662470.4284260 |
| 41. Total Acreage in Present Propert | y: . 42. Acreage Incl | uded in Nominated Boundary: |
| 43. Site Plan and Boundary Description | on and Justification: | |
| Site enclosed by | R. | ,N |
| Dite enclosed by No. a.B. C.D. E. Fas shown. | Olio R. | De diairion - |
| Includes the stone house | | more l |
| and lag quarters. | C | |
| Haundary drawn to | | |
| efelude houses in | | <u> </u> |
| Quenn acres Subdivision | | More house |
| | | |
| | | Blagguaren A |
| in the second se | | |
| • | | all horse |
| | M | B |

44. Description and House Plan:

Three bay, two-story, central passage dry stone house on high basement, size ca. 22 X 42. There are interior chimneys in each end. All lintels are wood beams, square wooden sills, 6/6 sash. Modillioned cornice across front, returned on ends of house. Front door four panel with transom, sidelights. Original mortar steeple pointed, had some cement, sandy; new repointing is concrete. Cellar entrance in east end. First floor door in east end also, indicates a wing or porch was there at some time.

Some odd features of the house are difficult to interpret: The roof is nearly flat behind the cornice, slopes slightly from front to back. The rear of the house has first floor of stucco, second of weatherboard; old frames. There is a vertical brea¢k in the masonry beside the east end door, isolating the southeast corner of the house into a column. These could indicate: planned expansion that didn't happen; a closed in gallery; a fire which burned the roof; a reduction in size of house; conservation of expense on the rear; changing styles, etc.—all antebellum. Interior not seen—there would be more clues there. There is a modern one story frame addition on the rear.

A log quarters faces the rear yard. It is two rectangular cells with chimney inside the larger.

Located on rise above the wide Ohio River valley and before a steep wooded hillside.