


D. Ransom Photo, 4/86
Negative: Connecticut
Historical Commission
FRONT ELEVATION, VIEW
SOUTHWEST



D. Ransom Photo, 4/86
Negative: Connecticut
Historical Commission
ROOF SOFFIT, NORTHEAST
CORNER, VIEW NORTHWEST



Warner House East Haddam. CT

Photograph 3

D. Ransom Photo, 4/86 Negative: Connecticut

Historical Commission FRONT PORCH, VIEW WEST



Warner House
East Haddam, CT
D. Ransom Photo, 4/86
Negative: Connecticut
Historical Commission

NORTH ELEVATION. VIEW

SOUTHEAST Photograph 4



VIEW NORTHEAST Photograph 5

Historical Commission




Warner House
East Haddam, CT

Photograph 6


D. Ransom Photo, 6/86
Negative: Connecticut
Historical Commission

FRONT STAIRWAY. VIEW WEST



D. Ransom Photo, 4/86 Negative: Connecticut Historical Commission

SOUTH FRONT ROOM, FIRST FLOOR, VIEW NORTHWEST



Negative: Connecticut Historical Commission SOUTHEAST DOOR, VIEW

SOUTHEAST Photograph 8



D. Ransom Photo, 4/86
Negative: Connecticut
Historical Commission
NORTH FRONT ROOM, FIRST
FLOOR, VIEW SOUTHWEST



Warner House
East Haddam, CT
D. Ransom Photo, 4/86
Negative: Connecticut
Historical Commission

Negative: Connecticut Historical Commission SOUTHWEST CORNER POST OF NORTH ROOM. VIEW SOUTH-

WEST



Warner House East Haddam, CT

Photograph 11

D. Ransom Photo, 4/86 Negative: Connecticut Historical Commission ORIGINAL AND RENEWED

STENCILING. NORTH ROOM. VIEW SOUTH



Warner House East Haddam, CT


Historical Commission KITCHEN, VIEW SOUTHEAST

East Haddam, CT
D. Ransom Photo, 4/86
Negative: Connecticut



Historical Commission SOUTH BEDROOM, VIEW

NORTHWEST Photograph 13



Negative: Connecticut
Historical Commission
NORTH BEDROOM, VIEW
SOUTHWEST




Negative: Connecticut Historical Commission REAR BEDROOM. VIEW

NORTHEAST Photograph 15



D. Ransom Photo, 4/86
Negative: Connecticut
Historical Commission
ATTIC, VIEW NORTHEAST
Photograph 16



Historical Commission BASEMENT, VIEW NORTHEAST



D. Ransom Photo, 4/86 Negative: Connecticut Historical Commission

BARN, VIEW SOUTH Photograph 18



Negative: Connecticut
Historical Commission
BURYING GROUND, VIEW
NORTHWEST



Negative: Connecticut Historical Commission SOUTH BASEMENT WINDOW, VIEW NORTHEAST