BENJAMIN SHOTWELL HOUSE # 1/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing northeasterly, front facade of house.

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 2/13
Edison Twp., Middlesex Co., N.J.
Photo 1986 by Arthur Brecknell
(negatives in photographer's file)

Facing easterly, close-up of shingled west gable and front facade of house

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 3/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing southerly, view of rear wall of house, showing 1840s section (left) attached to house, low stone rubble foundation, and water table

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 4/13
Edison Twp., Middlesex Co., N.J.

Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing south, close-up of wall of original house, showing small grilled window to lower level milk room and 9/6 sash in rear room

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 5/18
Edison Twp., Middlesex Co., N.J.

Photographer, Arthur Brecknell
(negatives in his file) 1986

Facing east, close-up of west gable wall showing surviving old shingles and low foundation

26 Ruengon's Lane

BENJAMIN SHOTWELL HOUSE # 6/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Close-up detail of course of shingled west gable wall, showing size and age of shingles

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 7/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing northwesterly, corner fireplace in original dwelling room (southwest room)

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 8/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing easterly, looking across front room of 1840s addition to den created out of original kitch= en leanto. (Fireplace opening has been closed.)

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 9/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing south, corner of sunken milk room, showing stone walls, step down, and rear face of paneled door

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 10/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing south, another view of corner of sunken milk room, showing paneled face of door leading to under-stairs area

26 Runyon's Lane



BENJAMIN SHOTWELL HOUSE # 11/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Detail: H-L hinge on rear flush face of paneled door between front and rear rooms of original house

26 Ranyon Lane

BENJAMIN SHOTWELL HOUSE # 12/13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing northwesterly, rear garret room, showing original half-height of wall and how it was raised in 1840s.

26 Runyon's Lane

BENJAMIN SHOTWELL HOUSE # 13of 13
Edison Twp., Middlesex Co., N.J.
Photo 1986, by Arthur Brecknell
(negatives in photographer's file)

Facing southerly, front garret room of 1840s addition, reached by a step down from original section

26 Runyon's Lane