

Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission VTEW WEST Photograph 1



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission VIEW NORTHWEST Photograph 2



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission VIEW SOUTHWEST Photograph 3



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission FRONT DOOR, VIEW WEST Photograph 4




Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission VIEW NORTHEAST Photograph 5




Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission FRONT STAIR. VIEW SOUTH-WEST Photograph 6



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission FIRST FLOOR, SOUTH ROOM, VIEW NORTHWEST Photograph 7




Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission FIRST FLOOR, SOUTH ROOM, VIEW SOUTHEAST Photograph 8



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission FIRST FLOOR, NORTH ROOM, VIEW SOUTHWEST Photograph 9



Whiting Homestead West Hartford. CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission KITCHEN FIREPLACE, VIEW SOUTHEAST Photograph 10




Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission FORMER BACK DOOR, VIEW SOUTHWEST Photograph 11



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Hisyorical Commission PRESENT KITCHEN, VIEW NORTHWEST Photograph 12



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission SECOND FLOOR, NORTH ROOM. VIEW SOUTHWEST Photograph 13



Whiting Homestead West Hartford. CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission SECOND FLOOR, NORTH ROOM, VIEW SOUTHEAST Photograph 14



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission ATTIC, VIEW NORTHEAST Photograph 15



Whiting Homestead West Hartford, CT D. Ransom Photo, 8/84 Negative: Connecticut Historical Commission BASEMENT. VIEW SOUTHEAST Photograph 16