

Vicinity of Elk City, Idaho
Photographed by John A. Feyk on 3 Nov. 1986;
negative at 2727 San Ramon Drive,
Rancho Palos Verdes, CA 90274
View (facing north) of cabin and surroundings.

Nezperce National Forest in background. Vandalized workshop at left. Red River runs between cabin and trees in the background. Old road runs between cabin and workshop.

Photograph no. 1.



Vicinity of Elk City, Idaho
Photographed by John A. Feyk on 3 Nov. 1986;
negative at 2727 San Ramon Drive,
Rancho Palos Verdes, CA 90274
View (facing morth) of sahin. Here are not to the same of the sahin.

View (facing north) of cabin. Hops are seen along the southwest wall. The metal roof was added to protect the cabin, the original roof being underneath.

Photograph no. 2.



Photograph no. 3.

Vicinity of Elk City, Idaho

Photographed by John A. Feyk on 3 Nov. 1986; negative at 2727 San Ramon Drive. Rancho Palos Verdes, CA 90274 View (facing south) of cabin. Sign requests that cabin not be vandalized. Collapsed porch is in foreground. Boards on northeast wall close off opening where storeroom was located.



Vicinity of Elk City, Idaho
Photographed by John A. Feyk on 3 Nov. 1986;
negative at 2727 San Ramon Drive
Rancho Palos Verdes, CA 90274
View (facing south) through the entrance

View (facing south) through the entrance door. Upper portion of staircase intact but lower portion, at a right angle, partially dismantled. Log pieces are used to fill the chinks.

Photograph no. 4.



Vicinity of Elk City, Idaho Photographed by John A. Feyk on 3 Nov. 1986; negative at 2727 San Ramon Drive. Rancho Palos Verdes, CA 90274 Closeup of wall adjacent to door (view facing northwest). Remanents of the newspaper wall covering remain. Photograph no. 5.