

Photograph 1
Applewood Farm from Col. Ledyard Hwy.
D.S.Plummer, 1/87
Applewood Farm

Negative on file at Ct Hist. Comm.

Ledyard, CT



Photograph 2
Farmhouse
D.S. Plummer, 12/86

Applewood Farm
Ledyard, CT
Negative on file at CT Hist. Comm.



Photograph 3
Corn Crib
D.S. Plummer
Applewood Farm
Ledyard, CT

Negative on file at CT Hist. Comm.



Photograph 4 Barn dairy shed, and silo D.S. Plummer, 1/87

Applewood Farm Ledyard, CT

Hartford, CT

Negative on file at CT Hist. Comm.



Photograph 5
Chicken coop and machinery shed
D.S.Plummer, 1/87
Applewood Farm
Ledvard, CT

Negative on file at CT Hist. Comm.




Photograph 6
Shed attached to house
D.S.Plummer, 10/85
Applewood Farm

Negative on file at CT Hist. Comm.

Ledyard, CT



Photograph 7 Farmhouse from west D.S. Plummer. 1/87 Applewood Farm Ledvard. CT Negative on file at CT Hist. Comm. Hartford, CT



Photograph 8 Gable end of wing, door detail D.S. Plummer, 10/85

Applewood Farm Ledvard. CT

Hartford, CT

Negative on file at CT Hist. Comm.



Photograph 9 Gable end of wing D.S. Plummer. 10/85

Applewood Farm

Negative on file at CT Hist. Comm

Ledvard. CT



Photograph 10 West side of ell D.S. Plummer, 10/85 Applewood Farm Ledyard, CT Negative on file at CT Hist. Comm. Hartford, CT



Photograph 11 Staircase in front entry

D.S.Plummer, 10/85

Negative on file at CT Hist. Comm.

Applewood Farm

Ledvard. CT



Photograph 12 Hall mantelpiece D.S.Plummer, 1/87 Ledyard, CT

Negative on file at CT Hist. Comm.

Applewood Farm



Photograph 13 Parlor mantelpiece D.S. Plummer, 1/87

Negative on file at CT Hist. Comm.

Applewood Farm

Ledvard. Ct



Photograph 14 Kitchen fireplace D.S. Plummer, 1/87 Applewood Farm

Negative on file at CT Hist. Comm.

Ledyard, CT



Photograph 15 Southwest bedroom fireplace D.S.Plummer, 1/87

Applewood Farm Ledyard, CT

Hartford, CT

Negative on file at CT Hist. Comm.