South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Streetscape
View Looking West
Photograph #1

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Streetscape
View Looking Southwest
Photograph #2

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Streetscape
View Looking Southeast
Photograph #3

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Streetscape
View Looing Southwest
Photograph #4

8

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: May, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: 8-10 South Willard Street
#1; View Looking Southeast
Photograph #5

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 16 South Willard Street,
#2; View Looking Northeast
Photograph #6

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 20 South Willard Street,
#3; View Looking East
Photograph #7

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: O.C. Taylor Residence-
Heart of Jesus; 28 South Willard; #4
Street; View Looking East
Photograph #8

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 34-38 South Willard
Street, #5; View Looking Northeast
Photograph #9

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: R.B. Steavns House;
#6; View Looking Northeast
Photograph #10

South Willard Street Historic District
Burlington, Vermont
Credit: Linda Seavey
Date: February, 1985
Negative filed at Vermont Division for
Historic Preservation
Description: The Worthern Residence
Building: #7; 50 South Willard Street
View: Looking Northeast
Photograph #11

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: H.W. Thompson House; #8;
54 South Willard Street
View Looking Northeast
Photograph #12

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: J.J. Thompson House; #9;
61 South Willard Street
View Looking Northeast
Photograph #13

NO PARKING
DRIVEWAY

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: J.J. Thompson House
Carriage Barn; #9A; 62 South Willard
Street; View Looking Southeast
Photograph #14

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 74 South Willard Street;
#11; View Looking East
Photograph #15

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 78 South Willard Street;
#12; View Looking East
Photograph #16

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Riordan Residence, #13;
80 South Willard Street
View Looking West
Photograph #17

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Paugbory House, #14
88 South Willard Street
View Looking East
Photogrpah #18

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Turk House, #15;
96-98 South Willard Street
View Looking Northeast
Photograph #19

THE MARANNETTE
APARTMENTS

South Willard Street Historic District
Burlington, Vermont
Credit: Linda Seavey
Date: February, 1985
Description: The Marannette Apartments
Building: #16; 360 College Street
View: Looking Northeast
Photograph #20

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Wires House; #17
118 South Willard Street
View Looking Northwest
Photograph #22

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: J. Henry McGreevy House;
#18; 130 South Willard Street
View Looking Northeast
Photograph #22

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: William H. Collins House;
#19; 138 South Willard Street
View Looking Northeast
Photograph #23

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 144 South Willard Street;
#20; View Looking Northeast
Photograph #24

NO
PARKING
THIS SIDE
OF STREET

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: William Wells; #21
158 South Willard Street
View Looking Northeast
Photograph #25

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 158 South Willard Street;
#21A; View Looking west
Photograph #26

South Willard Street Historic District
Burlington, Vermont
Credit: Daniel Zilka
Date: April, 1984
Negative Filed at Vermont Division
for Historic Preservation
Description: Parlor, Fireplace; Mantel
and Surround; William Wells Mansion; #21; 128 S. Willard St.
Photograph #27

South Willard Street Historic District
Burlington, Vermont
Credit: Daniel Zolka
Date: April, 1984
Negative Filed at Vermont Division
for Historic Preservation
Description: Interior, Central Hall
Main Staircase
Photograph #28

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 174 South Willard Street;
#22; View Looking East
Photograph #29

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: John Dewey House; #23
186 South Willard
View Looking Northwest
Photograph #30

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: 190 Jackson Center; #24
View Looking West-Northwest
Photograph #31

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Wells-Jackson Carriage
House; #25
View Looking Southeast
Photograph #32

196
JACKSON CT

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Leaven Worth House; #26
196 South Willard Street
View Looking Southeast
Photograph #33

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
description: Carriage Barn; #26A
196 South Willard Street
View Looking Southeast
Photograph #34

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: L.A. Walker House; #27
204 South Willard Street
View Looking Northeast
Photograph #35

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: L.A. Walker House; #27
204 South Willard Street
View Looking Southeast
Photograph #36

NO
PARKING
THIS SIDE
OF STREET

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: George Besset House; #28
216 South Willard Street
View Looking Northeast
Photograph #37

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 372 Maple Street; #29
View Looking Northeast
Photograph #38

CHAMPLAIN COLLEGE

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Edward Lyman House; #30
View Looking Southeast
Photograph #39

South Willard Street Historic District
Burlington, Vermont
Credit: Linda Seavey
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 246 South Willard Street;
#31; View Looking East
Photograph #40

South Willard Street Historic District
Burlington Vermont
Credit: Diane Conard
Date: January, 1985
Negative Filed at Vermont Division For
Historic Preservation
Description: A.B. Fisher-C.R. Turrill
Residence; #32
View Looking East
Photograph #41

CHAMPLAIN COLLEGE
THE
JOYCE
LEARNING
CENTER

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conrad
Date:

Date: January, 1985
Negative Filed at Vermont Division For
Historic Preservation
Description: Carriage Barn #32A
View Looking East
Photograph # 42

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 270 South Willard Street;
#34; View Looking East
Photograph #43

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 292 South Willard Street
#35; View Looking East
Photograph #44

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 416 South Willard Street;
#36; View Looking East
Photograph #45

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: B. Bullock House; #37
426 South Willard Street
View Looking Northeast
Photograph #46

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 436 South Willard Street;
#38; View Looking Southeast
Photograph #47

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Erald F. Foster House;
#39; View Looking Northeast
Photograph #48

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 452 South Willard Street
#40; View Looking East
Photograph #49

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: D.D. Howard Residence;
#41; 462 South Willard Street
View Looking Northeast
Photograph #40

480

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 480 South Willard Street
#43; View Looking Southeast
Photograph #61

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 498 South Willard Street
#44; View Looking East
Photograph #52

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Jonathan R. McLarsen, Jr.
#45; 500 South Willard Street
Photograph #53

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 504 South Willard Street
#46; View Looking Northeast
Photograph #54

BEECH ST

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 505 South Willard Street
#47; View Looking Northwest
Photograph #55

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 497 South Willard Street
#48; View Looking Northwest
Photograph #56

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Dudley Calhoun-Johnson-
Shephard Residence; #49; 487 South
Willard Street; View Looking Northwest
Photograph #57

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: August, 1988
Building: #50; 475 South Willard Street
View: Looking North west
Photograph #58

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: West side of South Willard
Street; #s 49, 50, 51
View Looking Southwest
Photograph #59

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Harris Walker House; #51
469 South Willard Street
View Looking Southwest
Photograph #60

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Harris H. Walker House-
Hitching Post; 469 South Willard
Street; #51; View Looking North
Photograph #62

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
description: 199 Howard Street; #52
View Looking South
Photograph #62

197

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 197 Howard Street; #53
View Looking Southwest
Photograph #63

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 173 Howard Street; #56
View Looking Southeast
Photograph #64

178
180

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Everitt I. Soule House;
#57; 178-180 Howard Street
View Looking Northeast
Photograph #65

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: William Tracy House; #58
184 Howard Street
View Looking Northeast
Photograph #66

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 190 Howard Street; #59
View Looking Northeast
Photograph #67

143

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 196 Howard Street; #60
View Looking North-Northeast
Photograph #68

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 200 Howard Street; #61
View Looking Northwest
Photograph #69

SPEED
LIMIT
30

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 457 South Willard Street
#63; View Looking West
Photograph #70

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 453 South Willard Street
#64; 443 South Willard Street; #65
View Looking Northwest
Photograph #68

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 439 South Willard Street
#66; View Looking West
Photograph #32

429

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 429 South Willard Street
#67; View Looking West
Photograph #73

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 425 South Willard Street
#68; View Looking Northwest
Photograph #74

315

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 415 South Willard Street
#69; View Looking Southeast
Photograph #75

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: Bartlett House; #70
405 South Willard Street
View Looking Northwest
Photograph #76

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Clarence Ward House #71
393 South Willard Street
View Looking Southwest
Photograph #77

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 385 South Willard Street
#72; View Looking Northwest
Photograph #78

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: 38 Cliff Street; #74
View Looking North
Photograph #78

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Herbert House; #75
46 Cliff Street
View Looking Northeast
Photograph #80

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Lorenzo Woodhouse House;
#78; 363 South Willard Street
View Looking Southwest
Photograph #81

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Charles W. Woodhouse House
#79; 349 South Willard Street
View Looking Southwest
Photograph #82

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Charles W. Woodhouse House
#79; rear 349 South Willard Street
View Looking East
Photograph #83

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 143 Spruce Street; #80
View Looking South-Southwest
Photograph #84

138

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 133 Spruce Street; #81
View Looking West
Photograph #85

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Sidney T. Greene House;
#82; 129 Spruce Street
View Looking Southeast
Photograph #86

132

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 132 Spruce Street; #83
View Looking North
Photograph #87

138

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 138 Spruce Street; #84
View Looking North
Photograph #88

South Willard Street Historic District
Burlington, Vermont
Credit: Linda Seavey
Date: February, 1985
Negative Filed at the Vermont Division
For Historic Preservation
Description: #85; 152 Spruce Street
View: North Northwest
Photograph #89

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Joseph Auld Residence;
#86; 170 Spruce Street
View Looking North
Photograph #90

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 331 South Willard Street
#87; View Looking West
Photograph #91

325

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 325 South Willard Street
#88; View Looking West
Photograph #92

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 321 South Willard Street
#89; View Looking Southwest
Photograph #93

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: T.B. Hanna-Joseph Smith
Residence; #90; 309 South Willard
Street; View Looking West
Photograph #94

ΣΦΜΔ

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: August, 1988
Description: Jensen Hall
Building: #91; 301 South Willard Street
View: Looking Southwest
Photograph #95

SQT
VERMONT

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Loomis Coach House; #91A
Tower Terrace
View Looking Southwest
Photograph #96

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 11 Tower Terrace; #92
View Looking Southwest
Photograph #97

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Henry Ballard House; #94
285 South Willard Street
View Looking Northwest
Photograph #98

ROWELL
HALL
CHAMPLAIN
COLLEGE
ROWELL HALL

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 275 South Willard Street
#95; View Looking North-Northwest
Photograph #99

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Addison Buell House; #96
267 South Willard Street
View Looking Northwest
Photograph #050

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Addison Buell House; #96
267 South Willard Street
View Looking Northeast
Photograph #106

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Edward J. Phelps House
#97; 251 South Willard Street
View Looking Northwest
Photograph #102

*

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Edward J. Phelps House
#97, 97A; 251 South Willard Street
View Looking Northwest
Photograph #103

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Edward J. Phelps House
#97B; 251 South Willard Street
Photograph #104

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 237 South Willard Street
#98; View Looking Southwest
Photograph #105

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: West side of South Willard
#s 98 & 99
View Looking Southwest
Photograph #101

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: 317 Maple Street; #100
View Looking South
Photograph #107

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: 315 Maple Street; #101
View Looking South
Photograph #108

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 305 Maple Street; #102
View Looking South-Southwest
Photograph #109

PRIVATE
PARKING

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 295 Maple Street; #103
View Looking South
Photograph #110

DATSUN
YV234

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 295 Maple Street; #103A
View Looking Southeast
Photograph #111

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 275 Maple Street; #105
View Looking Southwest
Photograph #112

FOR SALE

South Willard Street Historic District
Burlington, Vermont
Credit: Linda Seavey
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 276 Maple Street; #106
View Looking Northwest
Photograph #108

225

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 278-280 Maple Street;
#107; View Looking Northeast
Photograph #124

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 284 & 288 Maple Street
#s 107 & 108
View Looking Northwest
Photograph #115



South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: E.A. Fuller House; #109
288 Maple Street
View Looking Northeast
Photograph #116

EDMUNDS
SCHOOL
COMPLEX

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Ferdinand Beech House
#110; 300 Maple Street
View Looking Northwest
Photograph #117

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 308 Maple Street; #111
View Looking Northeast
Photograph #118

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 312 Maple Street; #112
View Looking North
Photograph #119

SPEED
LIMIT
25

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 225 South Willard Street
#113; View Looking Southwest
Photograph #128

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Drew House-Whiting Hall
#114; 203 South Willard Street
View Looking West
Photograph #127

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: January, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Carriage Barn; #114A
View Looking West
Photograph #12

CHAMPLAIN
COLLEGE

South Willard Street Historic District
Burlington, Vermont
Credit: Linda Seavey
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 163 South Willard Street
#115; View Looking Southeast
Photograph #128

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: James W. Hickok Estate
#116; 143 South Willard Street
View Looking Northwest
Photograph #129

South Willard Street Historic District
Burlington, Vermont
Credit: Thomas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 129-125-121 South Willard
Street; #s 117, 118, 119
View Looking Northwest
Photograph #125

NO
TURN
ON
RED
NISSAN

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: Steven Herrick House;
#120; 349 College Street
View Looking Southwest
Photograph #126

86
1003

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 121 South Willard Street
#121; View Looking North-Northwest
Photograph #127

South Willard Street Historic District
Burlington, Vermont
Credit: Peter Haller
Date: March, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 91-93 South Willard Street
#122; View Looking West
Photograph #128

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 87-89 South Willard Street
#123; View Looking North
Photograph #129

79

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: David Manson House; #124
79 South Willard Street
View Looking Southwest
Photograph #135

BRADLEY ST
S WILLARD ST

South Willard Street Historic District
Burlington, Vermont
Credit: Christine B. Lozner
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Third Congregational
Parsonage; #125; 71 South Willard
Street
Photograph #134

61
PATIENT PARKING ONLY
← PATIENT PARKING
COMPREHENSIVE
DENTAL CARE

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: April, 1988
Negative Filed at Vermont Division
for Historic Preservation
Description: 61 South Willard Street
#126; View Looking Northwest
Photograph #132

South Willard Street Historic District
Burlington, Vermont
Credit: Thmas D. Visser
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Richard Spear House; #127
55 South Willard Street
View Looking Southwest
Photograph #133

BUELL ST

South Willard Street Historic District
Burlington, Vermont
Credit: Ray Zirblis
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 45 South Willard Street
#128; View Looking North-Northwest
Photograph #134

South Willard Street Historic District
Burlington, Vermont
Credit: Diane Conard
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation.
Description: J.S. Patrick Residence
#129; 41 South Willard Street
View Looking Southwest
Photograph #135

South Willard Street Historic District
Burlington, Vermont
Credit: Clare Lise Kelly
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 29-33 South Willard Street
#130; View Looking West
Photograph #136

South Willard Street Historic District
Burlington, Vermont
Credit: Terri Griffith
Date: April, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: 19-21 South Willard Street
#132; View Looking North
Photograph #137

South Willard Street Historic District
Burlington, Vermont
Credit: Meryl Oliver
Date: February, 1985
Negative Filed at Vermont Division
for Historic Preservation
Description: Ed Revere Apartment
Building; #133; 17 South Willard
Street; View Looking Southwest
Photograph #138