

2903

NOV 15 1988

KENTUCKY HISTORIC RESOURCES  
Individual Inventory Form

Resource # 211  
Shelby County

1. Name of Resource:  
Dr. Nash House

2. Original Owner:  
Dr. Nash ?

3. Other Names:  
none

4. Prehistoric Site \_\_\_\_\_ Building x Object  
Historic Site \_\_\_\_\_ Structure \_\_\_\_\_ Other \_\_\_\_\_

5. Location:  
south side U.S. 60, Clay Village

6. Owner's Name:  
Th. Hodges [ P ]

7. Owner's Address:  
Rt. 3. Shelbyville 40065

8. Evaluation: [ N ]

9. Recognition & Date:  
Nat.Landmark \_\_\_\_\_ Local Landmark \_\_\_\_\_  
Nat.Register \_\_\_\_\_ HABS/HAER \_\_\_\_\_  
Highway Marker \_\_\_\_\_ KY Inventory 1980 ?  
KY Landmark Certificate \_\_\_\_\_

10. N.R.Status & Date:

11. N.R.Group:  
District Name: [ ]  
Mult.Resource Area: Shelby County [ ]  
Thematic Name: [ ]

12. Historical Theme:  
Primary: Architecture [ 030 ]  
Secondary: [ ]  
Other: [ ]

13. Statement of Significance:  
This property is significant under criterion C as a well-preserved example of the late-19th century (1865-1900) 2-story frame, side-passage plan in Shelby County. It is one of three such house identified in the county from the period. The side-passage form is traditionally [ C ]

14. History:  
considered an urban form and is rare in Shelby County. Alterations have not seriously affected the significant form and details of the house. The circular cellar building is a good example of food storage structures in region.

16. Date:  
Original Building 1870's [ 5 ]  
Addition [ ]

17. Style:  
Vernacular [ V ]  
[ ]

18. Architect/Builder:  
Unknown

19. No. of Stories: 2 [ 2.0 ]

20. Original Floor Plan:  
Side-passage [ SP ]

21. Single Pile X Double Pile N.A.

22. Roof Form & Material: Original x  
Gable / Asphalt shingle Not Original

23. Structural Material:  
Wood frame [ W ]

24. Exterior Material:  
sawn weatherboard [ W ]  
[ ]

25. Foundation Material:  
Stone coursed rubble [ S ]

26. Major Alterations: None  
Moved/Rebuilt Other  
x Additions porch enclosed

27. Special Features:  
none

28. Outbuildings:  
stone cellar [ 1 ]

29. Original Function:  
Residential/Domestic, single dwelling [ O1A ]

30. Present Use:  
as above [ O1A ]

31. Condition:  
Excellent [ E ]

32. Endangered: Yes \_\_\_\_\_  
No x

33. Attach Photos:  
Roll: Photo Nos: No. of Slides:  
17 13-17 1

15. Source of historical information and/or contact person: 1979 survey form  
info. from Th. Hodges

34. Prepared by: C. Worsham

35. Organization: Shelby County Hist Society

36. Date: April 1986

37. New Survey \_\_\_\_\_ Resurvey x

KENTUCKY HISTORIC RESOURCES  
Individual Inventory Form

Resource # 211

38. UTM Point of Primary Building: Quadrant: <u>Waddy</u>	Zone <u>16</u>	Easting <u>665500</u>	Northing <u>4228660</u>	39. G.I.S. Mod. [ ]
				40. Coordi.Accuracy [ ]


41. UTM Points of Boundary (for N. R. eligible sites only):

A. -----	D. -----
B. -----	E. -----
C. -----	F. -----

42. Total Acreage in Present Property: <u>21.97</u>	43. Acreage included in proposed N.R. boundary: <u>1.04</u>
---	---

44. Site Plan (and boundary description and justification for N.R. sites):

Beginning at point A on the south side of U.S. 60 and proceeding south 350 feet along a property and tree line to point B, thence west 130 feet along a fence to point C, thence north 350 feet along the east side of a drive to point D, thence 130 feet along the south side of U.S. 60 to the point of origin. The boundaries were drawn to include the main house and domestic space enclosed by fences, property lines, a drive, and the highway, and includes a contributing circular domed cellar, and a non-contributing frame shed. Not included is a tobacco barn to the south.



Point A is located at the intersection of a tree and property line defining the eastern edge of the yard with the southern edge of U.S. 60, and is 91 feet northeast of the northeastern corner of the house.

45. Description and House Plan:

Exterior: 2-story 3-bay frame side-passage plan dwelling. Narrow weatherboard, 6/6 sash windows, original blinds, returned cornice at gable ends, slightly projecting brick shouldered chimney at west gable end. One-story hip-roofed porch of three bays: chamfered posts support sawn brackets, panelled frieze with dentillated cornice. 2-story ell w/2 rooms per floor, chimney between rooms. 2-story porch along east wall of ell enclosed on 1st floor and end of second floor. End enclosure on each floor appears original. 2nd floor retains sq. columns w/necking, sawn flat balusters in railing.

Interior: ramped and eased rail on open-stringer stair in entry passage, with plain stringer and sq. balusters. Eared trim in room in main section as well as plain pilastered mantel.

Outbuildings: A contributing circular underground cellar w/ a concrete block entry just east of the end of the ell, and a non-contributing board-and batten frame shed. The nominated area includes two contributing buildings,

