



- 1) Name of Property: North Bend Ranger Station,  
Dwelling #1030
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking north, view of south-facing  
main facade, attached garage
- 7) Photograph Number: 05-05-1030-1



- 1) Name of Property: North Bend Ranger Station,  
Equipment Repair #2130
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking northwest, view of  
south-facing main facade and right elevation
- 7) Photograph Number: 05-05-2130-1



- 1) Name of Property: North Bend Ranger Station,  
Fire Management Warehouse #2033
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking southwest, view of main and  
right elevations
- 7) Photograph Number: 05-05-2033-1



- 1) Name of Property: North Bend Ranger Station,  
West Entrance
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking southeast, view of west  
entrance, section of post and rail fence
- 7) Photograph Number: 05-05-WE-1



- 1) Name of Property: North Bend Ranger Station,  
Carpenter Shop #2231
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking west, view of east-facing  
rear elevation
- 7) Photograph Number: 05-05-2231-2



- 1) Name of Property: North Bend Ranger Station,  
Crewhouse #2034
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking south, view of rear  
elevation
- 7) Photograph Number: 05-05-2034-2



- 1) Name of Property: North Bend Ranger Station,  
Crewhouse #2034
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking north, view of main facade
- 7) Photograph Number: 05-05-2034-1



- 1) Name of Property: North Bend Ranger Station,  
Fire Warehouse #2230
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking northwest, view of  
east-facing main facade and left elevation
- 7) Photograph Number: 05-05-2230-1



- 1) Name of Property: North Bend Ranger Station,  
Carpenter Shop #2231
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking northeast, view is of  
west-facing main facade and south elevation
- 7) Photograph Number: 05-05-2231-1



- 1) Name of Property: North Bend Ranger Station,  
Detail-South Entrance
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking north, detail of south  
entrance showing quality of materials, workmanship
- 7) Photograph Number: 05-05-SE-2



- 1) Name of Property: North Bend Ranger Station,  
South Entrance
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking north, view of south  
entrance
- 7) Photograph Number: 05-05-SE-1



- 1) Name of Property: North Bend Ranger Station,  
Recreation Office #2032
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking northwesterly, view of main  
entry, south elevation
- 7) Photograph Number: 05-05-2032-1



- 1) Name of Property: North Bend Ranger Station,  
Recreation Office #2032
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking west, view of east  
elevations
- 7) Photograph Number: 05-05-2032-2



- 1) Name of Property: North Bend Ranger Station,  
Ranger's Dwelling #1031
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking northeast, view of main  
facade, right elevation and attached garage.
- 7) Photograph Number: 05-05-1031-2



- 1) Name of Property: North Bend Ranger Station,  
Ranger's Dwelling #1031
- 2) City and State: North Bend, WA
- 3) Photographer: Ken White
- 4) Date: 10/84
- 5) Negative Location: USDA Forest Service, Regional  
Office, Recreation Unit, CRM files.
- 6) Description: Looking northeast, view of  
south-facing main facade and left elevation
- 7) Photograph Number: 05-05-1031-1