Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Facade of House Camera Facing North
1 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Facade of Log Section. Camera Facing Northwest.
2 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901

Facade of 1780 Stone Section. Camera Facing Northwest
3 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Rear of Building. Camera Facing Southeast.
4 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Side of 1780 Stone Section with Datestone
in Gable. Camera Facing East
5 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Side of Building Including Log Section and Rear Lean-to Addition. Camera Facing Southwest.
6 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Detail of Log Facade Showing Filled-in Window and Notches For Floor Joists. Camera Facing North.
8 of 18



Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Anne Wilson
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Detail of Log Facade, Camera Facing North
9 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Anne Wilson
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Portion of Log Wall, Door Jamb and Sill Supported by Stone Foundation Wall in Lean-to Section.
Camera Facing Southeast.
10 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Anne Wilson
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Boxed-In, Winder-Stair Leading to Second Floor.
in First Floor of Log Section of House.
Camera Facing East
11 of 18

C·S·1780

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Detail of Datestone in Gable of 1780 Stone Section of House. Camera Facing East.
12 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Anne Wilson
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Detail of Scars Indicating Possible Location of Corner Cupboard or Bar. First Floor of 1780 Stone Section. Camera Facing Northwest.
13 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Anne Wilson
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Square Area Indicating Location of Former Boxed-In
Winder-Stair. Ceiling of Second Floor Hall of 1780
Stone Section. Camera Facing North
14 of 18

Charles Springer House and Tavern (N-507)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Anne Wilson
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Original Closet Door and Door Leading to the Hall of the 1780 Stone Section.
Camera Facing East
15 of 18

Charles Springer House and Tavern (N-507.1- 507.12)
Moses Journey Barn (N-507.2 or N-508)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Stone Walls of 1852 Moses Journey Barn
Camera Facing Northwest
16 of 18

Ruins of Springhouse (N-507.3)
Charles Springer House and Tavern (N-507.1-507.12)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901
Ruins of Springhouse (N-507.3). Camera Facing Southeast.
17 of 18

Charles Springer House and Tavern (N-507.1 - N-507.12)
Four Mile Marker (507.4)
4921 Lancaster Pike
Wilmington, Christiana Hundred, Delaware 19807
Valerie Cesna
February, 1990
State of Delaware
Bureau of Archaeology and Historic Preservation
15 The Green
Dover, DE 19901

Four Mile Marker Indicating Distance to Wilmington
Camera Facing Northeast
18 of 18