



Gilkerson, William and Agnes, Farm  
Barnet, Caledonia Co., Vermont

92-27

Credit: William Bentley

Date: March 1992

Negative on file at Vermont

Division for Historic Preservation

View: South and east facades of house (# 1)

Photo 1



Gilkerson, William and Agnes, Farm  
Barnet, Caledonia Co., Vermont

Credit: William Bentley

Date: March 1992

Negative on file VT Div. for Historic  
Preservation

View looking SE; N+W facades (rear  
and side) of house. (#1)

photo 2

92-27



Gilkerson, William and Agnes, Farm  
Barnet, Caledonia Co., Vermont

Credit: William Bentley

Date: March 1992

Negative on file at Vermont Division  
for Historic Preservation

View looking W; interior W. wall of  
Kitchen (bldg #1)

photo 3

92-27



Gilkerson, William and Agnes, Farm  
Barret, Caledonia Co., Vermont  
Credit: William Bentley

Date: March 1992

Negative on file at VT Division for  
Historic Preservation

View looking ENE; west and south  
facades of bldgs # 2 and 3

PHOTO 4





Gilkerson, William and Agnes, Farm  
Barnet, Caledonia Co., Vermont  
Credit: William Bentley

Date: March 1992

Negative on file at VT Division for  
Historic Preservation

View looking E, interior of  
upper barn (# 36)

photo 5



Gilkerson, William and Agnes, Farm  
Barnet, Caledonia Co., Vermont  
Credit: William Bentley

Date: March 1982

Negative on file at VT Div. for  
Historic Preservation

View looking N; south facades of  
bldgs # 4b, 4a, and 3b

photo b



Gilkerson, William and Agnes, Farm  
Barnet, Caledonia Co., Vermont  
Credit: William Bentley

Date: March 1992

Negative on file at VT. Div. for  
Historic Preservation

View looking NNW, #5 (barn  
foundation)

Photo # 7