1303

NPS Form 10-900 (Rev. 10-90)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES REGISTRATION FORM

OMB No. 1024-0018

RECEIVE 4 6 6

OG 6 1996

This form is for use in nominating or requesting team that the stock of the individual properties and districts. See instructions of the National Register of Historic Places Registration Form (National Register Bulletin 16A). Complete each item by marking "x" in the appropriate box or by entering the information requested. If any item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions. Place additional entries and narrative items on continuation sheets (NPS Form 10-900a). Use a typewriter, word processor, or computer, to complete all items.

1. Name of Property	جہ جب <u>دی دی رہ</u> کہ خد خد کا ابنی وی د
historic name <u>Davidson Lake Shelter Cabin</u>	
other names/site number 49SIT-367	
2. Location	
street & number Admiralty Island National Monument	
not for publication <u>N/A</u>	
city or town Angoon	vicinity X
state Alaska code AK county Skagway-Yakutat-Angoon	code _231
zip code _99820	

USDI/NPS NRHP Registration Form 49SIT-367, Davidson Lake Shelter Cabin		
Skagway-Yakutat-Angoon, Alaska Civilian Conservation Corps Historic Pro	operties in Alaska	Page 2
3. State/Federal Agency Certification		
As the designated authority under the Na 1986, as amended, I hereby certify that for determination of eligibility meets tregistering properties in the National Emeets the procedural and professional references. In my opinion, the property me Register Criteria. I recommend that this significant nationally statewide continuation sheet for additional commendation.	this nomination _ the documentation stand Register of Historic Pl equirements set forth i sets does not meet s property be consider e locally. (S	request ards for aces and n 36 CFR Part the National
Signature of certifying official	10-2-9	· C
Signature of certifying official	<u>10-2-9</u> Date	
Federal Preservation Officer Forest Ser	vice	
State or Federal agency and bureau		
In my opinion, the property X meets Register criteria. (See continuation)	on sheet for additional	comments.)
Signature of commenting or other official	norch3, 190 Date	
Alaska State Historic Preservation Off	icer	
State or Federal agency and bureau		
4. National Park Service Certification		
I, hereby certify that this property is:	Edson Ball National Register.	11.2.95
other (explain):		

Signature of Keeper Date of Action

USDI/NPS NRHP Registration Form 49SIT-367, Davidson Lake Shelter Cabin Skagway-Yakutat-Angoon
Civilian Conservation Corps Historic Properties in Alaska Page 3
5. Classification
Ownership of Property (Check as many boxes as apply) private public-local public-StateX public-Federal
Category of Property (Check only one box)
Number of Resources within Property
Contributing Noncontributing
Number of contributing resources previously listed in the National Register $\underline{0}$
Name of related multiple property listing (Enter "N/A" if property is not part of a multiple property listing.) Civilian Conservation Corps (CCC) Historic Properties in Alaska; Admiralty Island Civilian Conservation Corps Canoe Route, 1933-1937
6. Function or Use
Historic Functions (Enter categories from instructions) Cat: Recreation & Culture Sub: Outdoor Recreation
Current Functions (Enter categories from instructions) Cat: Recreation & Culture Sub: Outdoor Recreation

Narrative Description (Describe the historic and current condition of the property on one or more continuation sheets.)

walls loq

other N/A

The Davidson Lake Shelter Cabin is a three-sided Adirondack style temporary shelter on the Admiralty Island Canoe Route that was constructed by Civilian Conservation Corps workers during the 1930s. It has a peeled log superstructure and shake walls and roof.

The structure is well-maintained, and its current appearance is similar to its original appearance. The sill logs have been replaced. Chainsaw cuts are visible on the replacements. Plywood shims were used to level the posts. The wall shakes are twenty inches long and abut vertically. None of the roof or wall shakes is original. Unlike many of the other shelter cabins on the canoe route, the front of the shelter does not have shakes protecting the ends of the horizontal poles used as nailers for the wall shakes. A painted box has been installed recently by the U.S. Forest Service to hold a visitors' register.

The natural context has not been changed since the shelter cabin was built. It overlooks Davidson Lake.

USDI/NPS NRHP 49SIT-367, Day	vidson Lake		in		
	ervation Co				Page 5
8. Statement	of Signific	ance			
	ional Regi	ster Criteri	a (Mark "x"	in one or	more boxes for
<u>X</u> A		is associate nt contribut			
В	Property in our pa		ed with the	lives of po	ersons significant
<u>x</u> c	period, o a master, significa individua	r method of or possessent and disti distinction	constructions high articles hi	n or repress stic values entity whos	ristics of a type, sents the work of s, or represents a se components lack
D		nas yielded, in prehisto			i information
Criteria Cons	iderations	(Mark "X" in	all the bo	exes that a	oply.) N/A
A	owned by purposes.	a religious	institution	or used for	or religious
B	removed f	rom its orig		on.	
c		ace or a gra	ve.		
D	a cemeter				
E		ructed build rative prope		, or struct	ure.
F		50 years of		nieved sign	ificance within
Areas of Sign:		nter catego: Entertainme)
		Architectu	:e		
Period of Sign	nificance	1933-1937		***************************************	
Significant Da	1935				
Significant Po		lete if Crit			ve)
Cultural Affi	liation N	/A			

Architect/Builder Civilian Conservation Corps

USDI/NPS NRHP Registration Form 49SIT-367, Davidson Lake Shelter Cabin Skagway-Yakutat-Angoon Civilian Conservation Corps Historic Properties in Alaska	
Narrative Statement of Significance (Explain the significance of property on one or more continuation sheets.)	
The Davidson Lake Shelter Cabin is a three-sided shelter built do 1930s by the Civilian Conservation Corps as part of the Admiralty Canoe Route. It is a good example of a three-sided Adirondack so shelter built for public recreation during the 1930s. The natural environment is unchanged from the time of the shelter's construct shelter has been maintained with materials similar to the original retains its integrity.	y Island tyle al tion. The
9. Major Bibliographical References	#
(Cite the books, articles, and other sources used in preparing to one or more continuation sheets.)	his form on
See Multiple Property Documentation Form	
Previous documentation on file (NPS) N/A preliminary determination of individual listing (36 CFR 67) requested. previously listed in the National Register previously determined eligible by the National Register designated a National Historic Landmark recorded by Historic American Buildings Survey # recorded by Historic American Engineering Record #	
Primary Location of Additional Data State Historic Preservation Office Other State agency X Federal agency Local government University Other Name of repository: Admiralty Island National Monument Juneau	

Name of repository: Admiralty Island National Monument, Juneau

USDI/NPS NRHP Registration Form 49SIT-367, Davidson Lake Shelter Cabin
Skagway-Yakutat-Angoon Civilian Conservation Corps Historic Properties in Alaska Page 7
10. Geographical Data
Acreage of Property less than one acre
UTM References (Place additional UTM references on a continuation sheet)
Zone Easting Northing Zone Easting Northing 1 08 537200 6384650 3
Verbal Boundary Description (Describe the boundaries of the property.)
The Davidson Lake Shelter Cabin is adjacent to a lake shore staging area and a trailhead, all within a circumscribed area of less than one acre in the SE 1/4 of the SE 1/4 of the SW 1/4 of Section 20, Township 49 South, Range 69 East, Copper River Meridian.
Boundary Justification (Explain why the boundaries were selected.)
The Davidson Lake Shelter Cabin has an obvious activity area arising from its function as a temporary stopping place on a recreational canoe route. The boundary encompasses the shelter cabin, lake shore staging area, and trailhead associated with the canoe route in the vicinity.
11. Form Prepared By
11. Form Prepared By ===================================
11. Form Prepared By
11. Form Prepared By name/title Charles M. Mobley, President organization Charles M. Mobley & Associates date September 28, 1992 street & number 200 West 34th St., #534 telephone (907) 653-1937
11. Form Prepared By name/title _Charles M. Mobley, President organization _Charles M. Mobley & Associates date _September 28, 1992 street & number _200 West 34th St., #534 telephone _(907) 653-1937 city or town _Anchorage state _AK _zip code _99503 Property Owner
11. Form Prepared By name/title _Charles M. Mobley, President organization _Charles M. Mobley & Associates date _September 28, 1992 street & number _200 West 34th St., #534 telephone _(907) 653-1937 city or town _Anchorage state _AK _zip code _99503
11. Form Prepared By name/title Charles M. Mobley, President organization Charles M. Mobley & Associates date September 28, 1992 street & number 200 West 34th St., #534 telephone (907) 653-1937 city or town Anchorage state AK zip code 99503 Property Owner
11. Form Prepared By name/title Charles M. Mobley, President organization Charles M. Mobley & Associates date September 28, 1992 street & number 200 West 34th St., #534 telephone (907) 653-1937 city or town Anchorage state AK zip code 99503 Property Owner (Complete this item at the request of the SHPO or FPO.)
11. Form Prepared By name/title Charles M. Mobley, President organization Charles M. Mobley & Associates date September 28, 1992 street & number 200 West 34th St., #534 telephone (907) 653-1937 city or town Anchorage state AK zip code 99503 Property Owner (Complete this item at the request of the SHPO or FPO.) name USDA Forest Service, Admiralty Island National Monument

USDI/NPS NRHP Registration Form

49SIT-367, Davidson Lake Shelter Cabin Skagway-Yakutat-Angoon, Alaska Civilian Conservation Corps Historic Properties in Alaska Page 8

ے بد سر ما ماہ ہے ہیں ہے جہ ہے ہیں ہیں ہے ہیں ہے۔ ماہ بد سر ماہ ہیں ہے ہی ہے جہ ہے ہیں ہے۔

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section Photograph identification

- 49SIT-367, Davidson Lake Shelter Cabin 1. Civilian Conservation Corps Historic Properties in Alaska Admiralty Island Civilian Conservation Corps Canoe Route, 1933-1937 Skagway-Yakutat-Angoon, Alaska Charles M. Mobley 8/12/92 (frame is labeled with incorrect date) Admiralty Island National Monument, Juneau Looking northeast at shelter cabin and activity area
- 2. 49SIT-367, Davidson Lake Shelter Cabin Civilian Conservation Corps Historic Properties in Alaska Admiralty Island Civilian Conservation Corps Canoe Route, 1933-1937 Skagway-Yakutat-Angoon, Alaska Charles M. Mobley 8/12/92 (frame is labeled with incorrect date) Admiralty Island National Monument, Juneau Looking south at structural members inside shelter