

DEC 28 1988

3252

KENTUCKY HISTORIC RESOURCES
Individual Inventory Form

Resource # Be-12
Boone County

1. Name of Resource: Clore house

2. Original Owner: Unknown

3. Other Names: None

4. Prehistoric Site Building X Object
Historic Site Structure Other

5. Location: 6001 Burlington Pike (KY 18) at intersection with Belleview Road

6. Owner's Name: Mrs. Catherine Clore []

7. Owner's Address: 6617 McVillie Rd. Belleview, KY

8. Evaluation: National Register []

9. Recognition & Date:
Nat.Landmark _____ Local Landmark _____
Nat.Register _____ HABS/HAER _____
Highway Marker _____ KY Inventory 1977
KY Landmark Certificate

10. N.R.Status & Date:

11. N.R.Group:
District Name: []
Mult.Resource Area: Boone County []
Thematic Name: []

12. Historical Theme:
Primary: Architecture []
Secondary: []
Other: []

13. Statement of Significance:
This property is significant under criterion C as a good local example of late 19th century (1850-1910) vernacular construction and as a rare instance of an urban house type (tall and narrow facade proportions, 3 rooms extending in file to the rear, side passage plan, exterior (Continued) []

14. History: Unknown

16. Date:
Original Building 1890s []
Addition []

17. Style:
No academic style []
[]

18. Architect/Builder: Unknown

19. No. of Stories: 2 []

20. Original Floor Plan:
side passage []

21. Single Pile Double Pile N.A. X

22. Roof Form & Material: Original X
gable/ st. sm. tin Not Original

23. Structural Material: wood frame []

24. Exterior Material: weatherboard []

25. Foundation Material: stone []

26. Major Alterations: None
Moved/Rebuilt Other
Additions X

27. Special Features: None

28. Outbuildings: none []

29. Original Function: dwelling []

30. Present Use: dwelling []

31. Condition: good []

32. Endangered: Yes
No X

33. Attach Photos:
Roll: 7 Photo Nos: 35-36 No. of Slides:
8 0-4

15. Source of historical information and/or contact person: N/A

34. Prepared by: Kenneth T. Gibbs

35. Organization: Boone Co.Hist.Pres.Rev.Brd.

36. Date: September 1986

37. New Survey _____ Resurvey X

KENTUCKY HISTORIC RESOURCES
Individual Inventory Form

Resource # Be-12


38. UTM Point of Primary Building: Zone Easting Northing 39. G.I.S. Mod. []
 Quadrant: Rising Sun 16 688440 4318100 40. Coordi.Accuracy []

41. UTM Points of Boundary (for N. R. eligible sites only):

A.	-----	D.	-----
B.	-----	E.	-----
C.	-----	F.	-----

42. Total Acreage in Present Property: 66.16 43. Acreage included in proposed N.R. boundary: .86

44. Site Plan (and boundary description and justification for N.R. sites):



The property is a rectangular parcel measuring 150' x 250', whose northwest corner is 20' directly northwest of the west row of mature maples and whose southeast corner is 30 feet southeast of the southeast corner of the house. The boundary includes the house and rows of maples that frame the facade. The minimum amount of land included is justified because the site, originally a farm, is compromised by the gravel pit to the south and because there are no outbuildings.

Contributing: 1 building

45. Description and House Plan:

Despite its rural site, this house is an urban house type. The main elevation is tall and narrow, and the plan consists of three rooms in file: parlor, dining room and kitchen. The side stair-passage extends only as deep as the parlor; behind this passage is an open porch, connecting the two rear rooms, and a pantry. The one-story addition at the rear served as a garage.

Exterior detailing focused on the main front: the foundation stones across the front are smooth-cut around the edges and rock-cut in the centers, while on the sides they are the less elaborate rock-cut; all the front windows have 1/1 panes, while those on the sides are 2/2 panes at the front rooms and the more old-fashioned 6/6 panes at the rear; only the front gable is ornamented with vertical tongue-in-groove boards.

The tall and narrow frontality of the house is emphasized by a double row of maples that frames the house and accentuates its role as a visual terminus of the Bellevue Road to the north. This key relation between the house facade and the T intersection of roads at which it is located has been preserved and helps mitigate the damage done to the site by the gravel pits to south, coming as close as 100' to the rear of the house.

13. Statement of Significance: (Continued)

detailing concentrated in the narrow facade) in a rural setting. Rural house types in the area, in contrast, are broader in their facade proportions, more laterally balanced in their plans, and their detailing more equally distributed among the four faces.

DEC 28 1988

3252

KENTUCKY HISTORIC RESOURCES
Individual Inventory Form

Resource # Be-12
Boone County

1. Name of Resource: Clore house

2. Original Owner: Unknown

3. Other Names: None

4. Prehistoric Site Building X Object
Historic Site Structure Other

5. Location: 6001 Burlington Pike (KY 18) at intersection with Belleview Road

6. Owner's Name: Mrs. Catherine Clore []

7. Owner's Address: 6617 McVillie Rd. Belleview, KY

8. Evaluation: National Register []

9. Recognition & Date:
Nat.Landmark _____ Local Landmark _____
Nat.Register _____ HABS/HAER _____
Highway Marker _____ KY Inventory 1977
KY Landmark Certificate

10. N.R.Status & Date:

11. N.R.Group:
District Name: []
Mult.Resource Area: Boone County []
Thematic Name: []

12. Historical Theme:
Primary: Architecture []
Secondary: []
Other: []

13. Statement of Significance:
This property is significant under criterion C as a good local example of late 19th century (1850-1910) vernacular construction and as a rare instance of an urban house type (tall and narrow facade proportions, 3 rooms extending in file to the rear, side passage plan, exterior (Continued) []

14. History: Unknown

16. Date:
Original Building 1890s []
Addition []

17. Style:
No academic style []
[]

18. Architect/Builder:
Unknown

19. No. of Stories: 2 []

20. Original Floor Plan:
side passage []

21. Single Pile Double Pile N.A. X

22. Roof Form & Material: Original X
gable/ st. sm. tin Not Original

23. Structural Material:
wood frame []

24. Exterior Material:
weatherboard []

25. Foundation Material:
stone []

26. Major Alterations:
Moved/Rebuilt None
Additions X Other

27. Special Features:
None

28. Outbuildings:
none []

29. Original Function:
dwelling []

30. Present Use:
dwelling []

31. Condition:
good []

32. Endangered: Yes
No X

33. Attach Photos:
Roll: 7 Photo Nos: 35-36 No. of Slides:
8 0-4

15. Source of historical information and/or contact person: N/A

34. Prepared by: Kenneth T. Gibbs

35. Organization: Boone Co.Hist.Pres.Rev.Brd.

36. Date: September 1986

37. New Survey _____ Resurvey X

KENTUCKY HISTORIC RESOURCES
 Individual Inventory Form

Resource # Be-12


38. UTM Point of Primary Building: Zone Easting Northing 39. G.I.S. Mod. []
 Quadrant: Rising Sun 16 688440 4318100 40. Coordi.Accuracy []

41. UTM Points of Boundary (for N. R. eligible sites only):

A.	-----	D.	-----
B.	-----	E.	-----
C.	-----	F.	-----

42. Total Acreage in Present Property: 66.16 43. Acreage included in proposed N.R. boundary: .86

44. Site Plan (and boundary description and justification for N.R. sites):



The property is a rectangular parcel measuring 150' x 250', whose northwest corner is 20' directly northwest of the west row of mature maples and whose southeast corner is 30 feet southeast of the southeast corner of the house. The boundary includes the house and rows of maples that frame the facade. The minimum amount of land included is justified because the site, originally a farm, is compromised by the gravel pit to the south and because there are no outbuildings.

Contributing: 1 building

45. Description and House Plan:

Despite its rural site, this house is an urban house type. The main elevation is tall and narrow, and the plan consists of three rooms in file: parlor, dining room and kitchen. The side stair-passage extends only as deep as the parlor; behind this passage is an open porch, connecting the two rear rooms, and a pantry. The one-story addition at the rear served as a garage.

Exterior detailing focused on the main front: the foundation stones across the front are smooth-cut around the edges and rock-cut in the centers, while on the sides they are the less elaborate rock-cut; all the front windows have 1/1 panes, while those on the sides are 2/2 panes at the front rooms and the more old-fashioned 6/6 panes at the rear; only the front gable is ornamented with vertical tongue-in-groove boards.

The tall and narrow frontality of the house is emphasized by a double row of maples that frames the house and accentuates its role as a visual terminus of the Bellevue Road to the north. This key relation between the house facade and the T intersection of roads at which it is located has been preserved and helps mitigate the damage done to the site by the gravel pits to south, coming as close as 100' to the rear of the house.

13. Statement of Significance: (Continued)

detailing concentrated in the narrow facade) in a rural setting. Rural house types in the area, in contrast, are broader in their facade proportions, more laterally balanced in their plans, and their detailing more equally distributed among the four faces.