m

**United States Department of the Interior** National Park Service

# National Register of Historic Places Continuation Sheet

Section number \_\_\_\_\_ Page \_\_\_\_

## SUPPLEMENTARY LISTING RECORD

NRIS Reference Number: 91001950 Date Listed: 1/13/92

<u>Little Mountain Lookout Tree</u> Property Name

<u>Coconino</u> <u>AZ</u> County State

<u>National Forest Fire Lookouts in the Southwestern Region TR</u> Multiple Name

\_\_\_\_\_

This property is listed in the National Register of Historic Places in accordance with the attached nomination documentation subject to the following exceptions, exclusions, or amendments, notwithstanding the National Park Service certification included in the nomination documentation.

<u>Unfaileth Afree</u> Signature of the Keeper <u>laskz</u> Date of Action

Amended Items in Nomination:

**Statement of Significance:** Under Areas of Significance, Engineering is added.

This information was confirmed with Evan DeBloois of the U.S. Forest Service.

DISTRIBUTION: National Register property file Nominating Authority (without nomination attachment)

1950

NATIONAL REGISTER	OF HISTORIC PLACES
REGISTRATION FORM	
······································	

NEXISTATION FORM	and the second se			
1. Name of Property				
historic name Little Mountain Lookout Tree				
other names/site number AR-03-07-03-1038				
	······································			
2. Location				
street & number N/A city, town Fredonia	/ /not for publication			
state Arizona code AZ county Coconir	/ x/vicinity no code 005 zip code 86022			
3. Classification				
Ownership of PropertyCategory of Property_privatepublic-localpublic-Statexxpublic-Federalobject	Number of Resources within Property         Contributing       Noncontributing			
Name of related multiple property listing:	Number of contributing resources previously listed in the National			
NATIONAL FOREST FIRE LOOKOUTS IN THE	Register			
SOUTHWESTERN RETION, USDA FOREST SERVICE				
4. State/Federal Agency Certification				
of eligibility meets the documentation standar National Register of Historic Places and meets requirements set forth in 36 CRF Part 60. In  _ does not meet the National Register criteri Signature of certifying official USDA - Forest Service	the procedural and professional my opinion, the property 4 meets a.   See continuation sheet.			
ODDA FOIESt Service				
In my opinion, the property meetsdoes not meet the National Register criteria.  _ See continuation sheet. Signature of certifying official				
C Nettenel Deel Comptee Contractor				
5. National Park Service Certification I, hereby, certify that this property is: I entered in the National Register. I See continuation sheet. I determined eligible for the National Register. I See continuation sheet.	Que 1/13/92			
<pre>[_ determined not eligible for the National Register. [_ removed from the National</pre>	<u></u>			
Register.				

6. Function or Use		
Historic Functions (enter categories	Current Functions (enter categories	
from instructions	from instructions)	
GOVERNMENT/ Lookout Facility	VACANT/NOT IN USE	
7. Description	······································	
	Matan 1 Jan Aran and an Oran	
Architectural Classification	Materials enter categories from	
(enter categories from instructions)	instructions)	
N/A	foundation	
	walls	
	roof	
	other N/A	
	roof	

Describe present and historic physical appearance.

## Summary

This isolated historic lookout tree is located on Little Mountain near Big Springs on the North Kaibab Ranger District, Kaibab National Forest. The tree is still alive and the ladder is intact. It is within an open Ponderosa pine forest on the Kaibab Plateau at an elevation of 7400 feet. This tree maintains sufficient integrity to qualify for National Register listing.

#### Physical Description

This lookout tree is ponderosa pine--110 feet tall and 3.5 foot in diameter--with a 60 foot tall ladder constructed up its north side. The entire ladder is intact and a toe hole is carved into the tree 2 feet above the ground. The five segments of ladder are in good condition. The construction is typical of other ladders on lookout trees: 2" X 4" lumber sidepieces with 1" x 12-14" crosspieces. It is attached to the tree with spikes.

#### Setting

Vegetation surrounding the site currently consists of an open mature Ponderosa pine forest with some grasses and forbs. The entire area is heavily littered with duff and downed vegetation. This area has been logged, but not recently and the setting retains much of its historic appearance. This tree offers a 360 degree view from its top.

#### Integrity

The Little Mountain Lookout Tree is still in good condition, despite having been abandoned for approximately 30 years. The entire ladder is intact. It is still readily identifiable as a lookout tree facility and retains integrity of location, design, feeling, material, workmanship, feeling, and association.

8. Statement of Significance		
Certifying official has considered the si other properties:	gnificance of this proper	ty in relation to
	ionally []statewide	$ \underline{\chi} $ locally
Applicable National Register Criteria $ \overline{\mathbf{x}} $	$A \mid \underline{=} \mid B \mid \underline{x} \mid C \mid \underline{=} \mid D$	
Criteria Considerations (Exceptions) $ $	A  _ B  _ C  _ D  _ E  _	F  _ G
Areas of Significance (enter categories from instructions)	Period of Significance	Significant Dates
Conservation		
Politics/Government	1905-1940	
	Cultural Affiliation N/A	
Significant Person	Architect/Affiliation	

# Summary

Little Mountain Lookout Tree is significant under Criterion A [36 CFR 60.6] for its association with 1) the development of forest fire prevention, detection, and control by the USDA Forest Service between 1905 and 1940, and 2) the conservation movement and its influence on public land management from 1905 to 1940. It is also significant under Criterion C [36 CFR 60.6] because it embodies the distinctive characteristics of a type of construction, the earliest and simplest form of fire detection structure, built into a living tree.

# Historic Contexts/Background

The construction and abandonment dates for the Little Mountain Lookout Tree are presently unknown. They might be ascertained, however, through oral history.

Although much remains to be learned about the history of this lookout tree, it had an important function in the earliest fire detection network on the Kaibab National Forest. It continues to evoke a sense of the past.

	See continuation sheet.
<pre>Previous documentation on file (NPS):     preliminary determination of individual     listing (36 CFR 67) has been requested.     previously listed in the National Regist     previously determined eligible by the         National Register     designated a National Historic Landmark     recorded by Historic American Buildings         Survey #         recorded by Historic American Engineerir         Record # </pre>	<pre>- Other State agency x Federal agency - Local government University Other</pre>
10. Geographical Data	WIIIIams, AZ
Acreage of property less than one	
UTM References         A  1 2         3 7 8 5 0 0         4 0 5 0 0 0 0          Zone       Easting       Northing         C	B
Verbal Boundary Description	
The boundary of the site is a square measu on the tree itself (see accompanying sketch	
Boundary Justification	
The boundary includes the lookout tree and	
	See continuation sheet
11. Form Prepared By	
	t Archaeologist North Kaibab RD
organization USDA Forest Service Kaibab Natl	
street & number <u>430 S. Main</u>	
city or town Fredonia	state AZ zip code 86022

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

PHOTOGRAPHS Page 1

THE FOLLOWING INFORMATION IS THE SAME FOR ALL PHOTOGRAPHS ACCOMPANYING THIS NOMINATION:

- 1). Little Mountain Lookout Tree
- 2). Vicinity of Grand Canyon, North Rim, southwest of Big Springs, Kaibab Plateau Arizona
- 3). John C. Davenport
- 4). May 1990
- 5). North Kaibab Ranger District, Kaibab National Forest, Fredonia, Arizona

INFORMATION FOR INDIVIDUAL PHOTOGRAPHS:

- 6). Facing south, tree in its setting.
- 7). #1
- 8). Facing southwest, closeup of ladder-works.
- 9). #2



