

Figure 1 Union Station White St., Danbury, Ct. 1918 photo, showing cover sheds, cresting and other roof details. Negative on file Scott-Fanton Museum 52 Main St., Danbury, Ct. 06810



Photograph 1 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin North and east elevation, looking southwest. Neg. on file Conn. Hist. Comm.



Photograph 2 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin West facade and north elevation, looking east. Neg. on file Conn. Hist. Comm.



Photograph 3 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin East elevation looking west. Neg. on file Conn. Hist. Comm.



Photograph 4 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin South entry facade, looking north Neg. on file Conn. Hist. Comm.



Photograph 5 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin West entry facade and south elevation, looking east Neg. on file Conn. Hist. Comm.



Photograph 6 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin West entry facade and south elevation, looking east Neg. on file Conn. Hist. Comm.



Photograph 7 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin Entries, north elevation Neg. on file Conn. Hist. Comm.



Photograph 8 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin Transom window, north elevation Neg. on file Conn. Hist. Comm.




Photograph 9 Union Station White St., Danbury, Ct. Oct. 1985 photo by W. Devlin Ticket window and wiaitng room (original express room) Neg. on file Conn. Hist. Comm.



Photograph 10 Union Station White St., Danbury, Ct. Jan. 1986 photo by W. Devlin Archway between entrance hall and general waiting room. Neg. on file Conn. Hist. Comm.



Photograph 11 Union Station White St., Danbury, Ct. Jan. 1986 photo by W. Devlin Main entrance hall, seen from general waiting room. Neg. on file Conn. Hist. Comm.



Photograph 12 Union Station White St., Danbury, Ct. Jan. 1986 photo by W. Devlin Fireplace, general waiting room Neg. on file Conn. Hist. Comm.



Photograph 13 Union Station White St., Danbury, Ct. Jan. 1986 photo by W. Devlin General waiting room (left) and main entrance ahll Neg. on file Conn. Hist. Comm.



Photograph 14 Union Station White St., Danbury, Ct. Jan. 1986 photo by W. Devlin Main ticket window, general waiting room Neg. on file Conn. Hist. Comm.



Photograph 15 Union Station White St., Danbury Co. Jan. 1986 photo by W. Devlin East wall, general waiting room Negative on file Conn. Hist. Comm.