Form KHC1985-2 Page 1 of \_\_\_\_\_ pages

KENTUCKY HISTORIC RESOURCES 2 8 1988 Resource #

ventory Form

3281

Resource	ŧ	Be-206
Boone		County

		Individual In
1.	Name of Resource	Hicks, Harvey A., House
2.	Original Owner:	
	•	Unknown
3.	Other Names:	
		None
4.		Building X Object
	Historic Site	Structure Other
5.	Location:	
		licks pike
	waito	n, κΥ
6.	Owner's Name:	
	-	
		lsie Jack []
7.	Owner's Address:	
		licks Pike
		n, KY 41094
8.	110.01	onal Register [ ]
9.		
	Nat.Landmark	Local Landmark
	Nat. Kegister	HABS/HAER KY Inventory 1977
	Highway Marker	KI Inventory 19//
10	KY Landmark Ce	
$\frac{10}{11}$	N.R.Status & Date N.R.Group:	۵۰ دارمند المراجع
11.	District Name:	, ,
		rea: Boone County [ ]
	Thematic Name:	
19	Historical Theme:	l
14.		rchitecture [ ]
	Secondary:	
	Other:	
13.	Statement of Signi	ficance:
	-	

This property is significant under criterion C as an unusual example of its plan and form, a kind of hybrid between a double pile, central passage house and an I-house. The house is the only known example of its type identified in the county and is significant to the Γ ]

## 14. History:

The owner in the 1883 atlas is H.A. Hicks. An owner previous to Hicks, who not the builder of either stage of the house, was a man named Menzies, from Fort Mitchell.

		~~~~~	
16.	Date:		
	<b>Original Building</b> 2nd $\frac{1}{4}$ 19th c.	I	1
	Addition 3rd 19th c.	ř	i
17	Style:	L	
1(.	Federal	г	1
	Greek Revival, Italianate	[	]
10	Architect/Builder:	l	<u> </u>
10.	unknown		
10		r	<u>1</u>
	No. of Stories: one/two	<u> </u>	
20.	Original Floor Plan:		-
	one-room /central passage	<u> </u>	]
		N.A.	
		nal	Χ
	gable/st. sm. tin Not Origi	nal 🗌	
23.	Structural Material:		
	log/wood frame	]	]
24.	Exterior Material: vinyl siding	1	Ī
	wood trim	Ī	i
25.	Foundation Material:	· · · · ·	<b>_</b> _
	stone	ſ	1
26	Major Alterations: None X	t	<u>_</u>
20.	Moved/Rebuilt Other		
	Additions $\chi$		
07			
	Special Features:	-	
	rame house is dbl-pile plan, I-h	<u>is. e</u>	<u>evat</u> io
28.	Outbuildings:	<b>r</b>	
	smokehouse, icehouse/cellar, pri	<u>vy l</u>	<u> </u>
29.	Original Function:	-	_
	farm dwelling	[	]
30.	Present Use: dwelling		
	-	]	]
31.	Condition:		
	good	]	]
32.	Endangered: Y	es	
	0	No OF	X
99			<u></u>
	Attach Photos:	• • •	
3	Roll: <sup>5</sup> Photo Nos: <sup>5-8</sup> No. of S	udes:	

15. Source of	historical	information	and/or	contact
person:				


•	-	Kenneth T. Gibbs
35.	Organization:	Boone Co.Hist.Pres.Rev.Brd.
36.	Date:	September 1986
37.	New Survey	Resurvey χ

owner

### KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource # \_\_\_\_\_Be-206\_

38.	UTM Point of Primary Building: Quadrant: Union	Zone	<b>Easting</b> 702720	Northing		G.I.S. Mod. Coordi.Accuracy	[	
	Quadrant: Union	<u>16</u>		_4309260	40.	Coordi.Accuracy	L	
41.	UTM Points of Boundary (for N. R	. eligible	e sites only):					
	A		Γ	).				
	B		E	l				
	c	_	F	•				
42.	Total Acreage in Present Property	1: 121.9	9 43. Acre	age included in p	oropose	d N.R. boundary:	2	
44.	Site Plan (and boundary descriptio	n and ju	stification fo	r N.R. sites):				
	Sty to DA.							
	D The Vy	N		Beainnina	at a	point 20' east c	of	
		R				the north side		
						proceed north 3		
						eed west for 250		



(D), turning south 350' to the north side of Hicks Pike (C). Then proceed 250' along Hicks Pike to the point of origin. The boundary includes the house and the three adjacent dependencies and suffi-

cient acreage to provide a setting.

#### 45. Description and House Plan:

C

house

trees

Hicks

The earliest section of the <u>house</u> is a square log pen, one story in height, that is now the northernmost room of the ell. The large, columned mantel in this room is late Federal in style, and the room has horizontal-board panelling on all four interior walls.

B

Pike

The rest of the house appears to have been built in a single stage as a large, frame addition. In plan this addition is double-pile with a divided central passage and a oneroom ell (joining the log pen to the main part of the house), but only the front, part, one-room deep, rises a full two stories. The second pile is roofed in two ways: the back half of the central passage and the right-rear chamber are shed-roofed, while the back-left room is gable-roofed, continuing the line of the log pen gable, giving the appearance of a three-room ell.

The interior woodwork of the frame addition blends Greek Revival and Italianate styles and is grained in several tones. A bathroom has been inserted in the back half of the central passage.

Although the house was recently vinyl-sided, care was taken to leave as much of the wooden detail as possible, including the bracketed cornice, the five-bay front porch, and the front door surrounds, and match the width of the weatherboarding. Despite the siding, the house readily conveys its distinctive traits through its form and plan.

There are two barns associated with the farmstead, but, since one is distant from the house and not visible from it and has its separate lane, and since the other is on the south side of Hicks Pike, under different ownership, they are not included in the boundaries. The smokehouse, icehouse and privy, however, are contiguous to the house and date from the period of significance of the house.

Resource #<u>Be-206</u> Boone County Page <u>3</u> of <u>3</u> Pages

# 13. Statement of Significance: (Continued)

county in the period 1800, the likely date of the first double pile houses in Boone County, to 1900, the end of the period of significance for I-houses in the county. Although the house has been vinyl-sided, original wooden detailing remains, and the significant overall form and plan have not been obscured. Form KHC1985-2 Page 1 of \_\_\_\_\_ pages

KENTUCKY HISTORIC RESOURCES 2 8 1988 Resource #

ventory Form

3281

Resource	ŧ	Be-206
Boone		County

		Individual In
1.	Name of Resource	Hicks, Harvey A., House
2.	Original Owner:	
	•	Unknown
3.	Other Names:	
		None
4.		Building X Object
	Historic Site	Structure Other
5.	Location:	
		licks pike
	waito	n, κΥ
6.	Owner's Name:	
	-	
		lsie Jack []
7.	Owner's Address:	
		licks Pike
		n, KY 41094
8.	110.01	onal Register [ ]
9.		
	Nat.Landmark	Local Landmark
	Nat. Kegister	HABS/HAER KY Inventory 1977
	Highway Marker	KI Inventory 19//
10	KY Landmark Ce	
10.	N.R.Status & Date N.R.Group:	۵۰ دارمند المراجع
11.	District Name:	, ,
		rea: Boone County [ ]
	Thematic Name:	
19	Historical Theme:	l
14.		rchitecture [ ]
	Secondary:	
	Other:	
13.	Statement of Signi	ficance:
	-	

This property is significant under criterion C as an unusual example of its plan and form, a kind of hybrid between a double pile, central passage house and an I-house. The house is the only known example of its type identified in the county and is significant to the Γ ]

## 14. History:

The owner in the 1883 atlas is H.A. Hicks. An owner previous to Hicks, who not the builder of either stage of the house, was a man named Menzies, from Fort Mitchell.

		~~~~~	
16.	Date:		
	<b>Original Building</b> 2nd $\frac{1}{4}$ 19th c.	I	1
	Addition 3rd 19th c.	ř	i
17	Style:	L	
1(.	Federal	г	1
	Greek Revival, Italianate	[	]
10	Architect/Builder:	l	<u> </u>
10.	unknown		
10		r	<u>1</u>
	No. of Stories: one/two	<u> </u>	
20.	Original Floor Plan:		-
	one-room /central passage	<u> </u>	]
		N.A.	
		nal	Χ
	gable/st. sm. tin Not Origi	nal 🗌	
23.	Structural Material:		
	log/wood frame	]	]
24.	Exterior Material: vinyl siding	1	Ī
	wood trim	Ī	i
25.	Foundation Material:	· · · · ·	<b>_</b> _
	stone	ſ	1
26	Major Alterations: None X	t	<u>_</u>
20.	Moved/Rebuilt Other		
	Additions $\chi$		
07			
	Special Features:	-	
	rame house is dbl-pile plan, I-h	<u>is. e</u>	<u>evat</u> io
28.	Outbuildings:	<b>r</b>	
	smokehouse, icehouse/cellar, pri	<u>vy l</u>	<u> </u>
29.	Original Function:	-	_
	farm dwelling	[	]
30.	Present Use: dwelling		
	-	]	]
31.	Condition:		
	good	]	]
32.	Endangered: Y	es	
	0	No OF	X
99			<u></u>
	Attach Photos:	• • •	
3	Roll: <sup>5</sup> Photo Nos: <sup>5-8</sup> No. of S	udes:	

15. Source of	historical	information	and/or	contact
person:				


•	-	Kenneth T. Gibbs
35.	Organization:	Boone Co.Hist.Pres.Rev.Brd.
36.	Date:	September 1986
37.	New Survey	Resurvey χ

owner

### KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource # \_\_\_\_\_Be-206\_

38.	UTM Point of Primary Building: Quadrant: Union	Zone	<b>Easting</b> 702720	Northing		G.I.S. Mod. Coordi.Accuracy	[	
	Quadrant: Union	<u>16</u>		_4309260	40.	Coordi.Accuracy	L	
41.	UTM Points of Boundary (for N. R	. eligible	e sites only):					
	A		Γ	).				
	B		E	l				
	c	_	F	•				
42.	Total Acreage in Present Property	1: 121.9	9 43. Acre	age included in p	oropose	d N.R. boundary:	2	
44.	Site Plan (and boundary descriptio	n and ju	stification fo	r N.R. sites):				
	Sty TC DA.							
	D The Vy	N		Beainnina	at a	point 20' east c	of	
		R				the north side		
						proceed north 3		
						eed west for 250		



(D), turning south 350' to the north side of Hicks Pike (C). Then proceed 250' along Hicks Pike to the point of origin. The boundary includes the house and the three adjacent dependencies and suffi-

cient acreage to provide a setting.

#### 45. Description and House Plan:

C

house

trees

Hicks

The earliest section of the <u>house</u> is a square log pen, one story in height, that is now the northernmost room of the ell. The large, columned mantel in this room is late Federal in style, and the room has horizontal-board panelling on all four interior walls.

B

Pike

The rest of the house appears to have been built in a single stage as a large, frame addition. In plan this addition is double-pile with a divided central passage and a oneroom ell (joining the log pen to the main part of the house), but only the front, part, one-room deep, rises a full two stories. The second pile is roofed in two ways: the back half of the central passage and the right-rear chamber are shed-roofed, while the back-left room is gable-roofed, continuing the line of the log pen gable, giving the appearance of a three-room ell.

The interior woodwork of the frame addition blends Greek Revival and Italianate styles and is grained in several tones. A bathroom has been inserted in the back half of the central passage.

Although the house was recently vinyl-sided, care was taken to leave as much of the wooden detail as possible, including the bracketed cornice, the five-bay front porch, and the front door surrounds, and match the width of the weatherboarding. Despite the siding, the house readily conveys its distinctive traits through its form and plan.

There are two barns associated with the farmstead, but, since one is distant from the house and not visible from it and has its separate lane, and since the other is on the south side of Hicks Pike, under different ownership, they are not included in the boundaries. The smokehouse, icehouse and privy, however, are contiguous to the house and date from the period of significance of the house.

Resource #<u>Be-206</u> Boone County Page <u>3</u> of <u>3</u> Pages

# 13. Statement of Significance: (Continued)

county in the period 1800, the likely date of the first double pile houses in Boone County, to 1900, the end of the period of significance for I-houses in the county. Although the house has been vinyl-sided, original wooden detailing remains, and the significant overall form and plan have not been obscured.