



Name: (BROWN) Dr. John A. House
The "Anchorage" N-4046

Location: 4 7th Avenue, Wilmington, Delaware
NEW CASTLE CO.

Photographer: Dean E. Nelson

Date: November, 1978

Location of Negative: Hall of Records, Dover, Delaware

Description: The mansion house and front yard, looking
north

Photograph Number: 1

FEB 22 1979

24 10773



(BROWN, DR. JOHN A., HOUSE)

Name: The "Anchorage" N-4046

NEW CASTLE CO

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Dean E. Nelson

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: The facade, illustrating the juxtaposition
of federal stone core, Italian Villa towers, and colonial
revival porch, looking west.

Photograph Number: 2

FEB 22 1979



(BROWN, Dr. John A., House)

Name: The "Achorage" N-4046

New Castle Co.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Dean E. Nelson

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: The north wall of the large Villa tower.

Photograph Number: 3

FEB 22 1979

APR 24 1979



(Brown, Dr. John T., House)

Name: The "Anchorage" N-4046

NEW CASTLE CO.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Dean Nelson

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: The rear of the mansion showing the small Italian Villa Tower and shed roofed kitchen wing. Looking to the southeast.

Photograph Number: 4

FEB 22 1979

24 1978



(BROWN, Dr. John A., House)

Name: The "Anchorage" N-4046

NEW CASTLE
CO.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Dean E. Nelson

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: The rear of the mansion looking to the east.

Photograph Number: 5

FEB 22 1979

FEB 24 1979



(BROWN) Dr. John A. House

Name: The "Anchorage" N-4046

NEWCASTLE Co.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Jean Athan

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: The King of Prussia marble mantel in the front
parlor of the original stone sidehall core. It was
probably added with the addition of the Italian Villa tower;
and replacing the original wooden Federal mantels.

Photograph Number: 6

24 1979

FEB 22 1979



(Brown, Dr. John A. House)

Name: The "Anchorage" N-4046

NEW CASTLE CO.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Jean Athan

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: a detail of the staircase.

Photograph Number: 7

FEB 22 1979

24 10/78



(Brown, Dr. John A., House)

Name: The "Anchorage" N-4046

NEW CASTLE
CO.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Jean Athan

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: A raised six panel door on the second floor.
Most of the earlier box locks have been replaced with
smaller later Victorian box locks as seen in this view.

Photograph Number: 8

FEB 22 1979

APR 24 1979



(Brown, Dr. John A., House)

Name: The "Anchorage" N-4046

NEW CASTLE Co.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Jean Athan

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: The front parlor chamber federal mantel and chimney closets. Note that the temporary room partition to the right is cut out to accommodate the mantel profile.

Photograph Number: 9

FEB 22 1979

APR 24 1979



Name: The "Anchorage" N-4046 (Browny Dr. John A. House)

NEW CASTLE Co.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Dean E. Nelson

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: The gable end facade of the stuccoed brick
outbuilding. Looking west.

Photograph Number: 10

APP 24 1979

FEB 22 1979



Name: The "Anchorage" N-4046

(Brow, Dr. John A., House)
NEW CASTLE CO.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Dean E. Nelson

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Facade of the frame Gothic carriage house,
looking south.

Photograph Number: 11

FEB 22 1979

24 1979



(Brown, Dr. John A., House)

Name: The "Anchorage" N-4046

NEW CASTLE CO.

Location: 4 7th Avenue, Wilmington, Delaware

Photographer: Dean E. Nelson

Date: November, 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Facade of frame dwelling, looking south

Photograph Number: 12

FEB 22 1979

APR 24 1979