

National City Bank (Merchant's Exchange)
55 Wall Street
New York, New York


Photo No. 1

By: George R. Adams

Negative at: Historic Sites Survey

Date: November 1976

View: Portion of east side and
entire front (north) facade.



National City Bank (Merchant's Exchange
55 Wall Street
New York, New York

Photo No. 2

By: George R. Adams

Negative at: Historic Sites Survey

Date: November 1976

View: East side



National City Bank Photo Credit: AASLH

National City Bank (Merchant's Exchange
55 Wall Street
New York, New York

Photo No. 3

By: George R. Adams

Negative at: Historic Sites Survey

Date: November 1976

View: The Exchange Room. East Wall
and portion of rear wall, showing
Southeast corner.