



# Coulterville Main Street Historic District

Overview of Coulterville  
looking east. Jeffery  
Hotel (1) is the three-  
story building in left cen-  
ter. New Rt. 49 bridge at  
right center.

Coulterville Historic Dist.  
Coulterville, CA.  
David Devey for Ann S. Peak  
& Associates. July 1977

1 of 31

FEB 8 1982



Coulterville Main Street Historic District  
view of Main Street

Steve Mikesell, photographer  
1220 K Street, Sacramento, CA

April 1981  
view to the East

2 of 31

FEB 8 1982



# Coulterville Main Street Historic District

Structures 1, 2, 3 & 4

1. Jeffrey Hotel
2. Magnolia Room
3. Commercial Building
4. Commercial Building

Coulterville, California

David Devey, 1977

Negative on file with

Peak & Associates, Inc.

Sacramento, CA 95826

Looking West

3 of 31

FEB 8 1982



Coulterville Main Street Historic District

Structures 1,2, 3, 4, 5, 6

Steve Mikesell, photographer

1220 K Street, Sacramento, CA

April 1981

view to the West

4 of 31

FEB 4 1982



Coulterville Main Street Historic District  
Structure 1

Steve Mikesell, photographer  
1220 K Street, Sacramento, CA

April 1981

view to the East

5 of 31

Feb 3 1982



Coulterville Main Street Historic District

Structures 5 and 6

Steve Mikesell, photographer

1220 K Street, Sacramento, Ca

April 1981

view to the Northeast

6 of 31

FEB 9 1982



Coulterville Main Street Historic District

Structure 5

Commerical Building  
(Villa Roma)

Coulterville, California

Melinda Peak, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking northwest



Coulterville Main Street Historic District

Structure 6

Garage

Coulterville, California

Melinda Peak, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking west

8 of 31

FEB 8 1982



ANTIQUE

Antiques

OPEN

*Coulterville Main Street Historic District*

Structure 7

Harlow House

Coulterville, California

David Devey, Aug. 1977

Neg. on file - Peak and  
Associates, Inc., Sacto.

Looking northwest

9 of 31

FEB 8 1982



CARREL BAY PUBLIC CO.

Coulterville Main Street Historic District

Structure 8

Canova Warehouse

Coulterville, California

Melinda Peak, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking northwest

10 of 31

FEB 8 1982



# Coulterville main Street Historic District

Structure 9

Sun Sun Wo, Store

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking south

11 of 31

FEB 8 1982



# Coulterville Main Street Historic District

Structure 10

Candy's House

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking east

12 of 31

FEB 8 1984



Coulterville Main Street Historic District

Structure 11

Canova House

Coulterville, California

Melinda Peak, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking southeast

13 of 31

FEB 8 1982



# Coulterville main Street Historic District

Structure 12

I.O.O.F. Hall

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking east

14 of 31

FEB 8

1902



Coulterville Main Street Historic District  
Structure 12

Steve Mikesell, photographer  
1220 K Street, Sacramento, CA

April 1981

view to the East

15 of 31

FEB 8

1982



Coulterville Main Street Historic District

Structure 13

Ellis House

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and  
Associates, Inc., Sacto.

Looking southeast

*16 of 31*

FEB 8 1982



Coulterville Main Street Historic District

Structure 14

Commissiona Store

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking east

17 of 31

FEB 8 1982



Coulterville Main Street Historic District  
Structures 15, 16, 17, and 181

Steve Mikesell, photographer

1220 K Street, Sacramento, CA

April 1981

view to the East

18 of 31



Coulterville Main Street Historic District

Structures 15, 16, 17 & 18

Gazzola Building

Commerical Buildings

Coulterville, California

Melinda Peak, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking east

19 of 31

FEB 8 1992



Coulterville Main Street Historic District

Structure 16

Commercial Building

Coulterville, California

Melinda Peak, April 1981

Neg. on file - Peak and

Associates, Inc., Sacto.

Looking northeast. Struc-

ture 15 in background

20 of 31

FEB 8 1982



# Coulterville Main Street Historic District

Structure 19

Residence

Coulterville, California

David Devey, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking west from Water St.

21 of 31

FEB 8 1982



Coulterville main street Historic District

Structure 20

Lawson Building (non-  
contributing)

Coulterville, California

Melinda Peak, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking east

22 of 31

FEB 8 1982



Coulterville Main Street Historic District

Structure 21

E.E. Warne Store

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking east

FEB 8 1982

23 of 31



Coulterville Main Street Historic District

Structure 22

Warehouse

Coulterville, California

Melinda Peak, April 1981

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking west from Water St.

24 of 31

FEB 8

1982



*Caulerwile Trade Post*  
GROCERIES MEAT BEER & WINES  
FISHING - BOATING TOOLS - HARDWARE

# Coulterville Main Street Historic District

Structure 23

Trading Post

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking southwest

25 of 31

FEB 8 1982



Coulterville Main Street Historic District  
Structure 23

Steve Mikesell, photographer

1220 K Street, Sacramento, CA

April 1981

view to the South

26 of 31

SEE 1832



# Coulterville Main Street Historic District

Structures 24 and 25

Coulter Hotel and

McCarthy Building

Coulterville, California

David Devey, Aug. 1977

Neg. on file-Peak and

Associates, Inc., Sacto.

Looking southwest

FEB 8 1982

27 of 31



Coulterville Main Street Historic District  
Structures 24 and 25  
Steve Mikesell, photographer  
1220 K Street, Sacramento, CA  
April 1981  
view to the Southeast  
28 of 31

FEB 8

1982



# Coulterville, Main Street Historic District

A stray caught in town in front of Warne store, Structure 21. Ruins of Structure 1 and structure 2, in far background.

Coulterville, California  
Photographer, unknown, 1900.

Negative on file-Peak &  
Associates  
Sacramento, California  
Looking east

29 of 31

FEB 8 1982



# Coulterville Main Street Historic District

First autos enroute to  
Yosemite.

Structures 23, 24, 25, 1,  
2, 3, and 4.

Coulterville, California  
Photographer unknown, 1913  
Negative on file-Peak &

Associates  
Sacramento, California  
Looking southwest

30 of 31

FEB 8 1982



DENTIST

*Martin Photo*  
*Miss of ...*

# Coulterville Main Street Historic District

Coulterville-Pleasant Valley  
stage in front of Structures  
2, 3, and 4.

Coulterville, California  
Photographer unknown, 1910  
Negative on file-Peak &  
Associates

Sacramento, California  
Looking northwest

31 of 31

FEB 8 1982