

Cains Coffee Company Building
Oklahoma City, Oklahoma

View from the S.W., looking at the front
(S.) side, and the west end.

DEC 22 1981 FEB 4 1982



Cains Coffee Company Building

Oklahoma City, Oklahoma

View from the S.E., looking at the east
end and the front side. Notice the close
proximity to the tracks.

FEB 4 1982

DEC 22 1981



Cains Coffee Company Building

Oklahoma City, Oklahoma

View from the N.E., looking at the back (N.) side, and the E. end. Notice the attached lean-to garage.

FEB 4 1982

DEC 22 1981



FEB 4 1982

Cains Coffee Company Building

Oklahoma City, Oklahoma

View from the S.E., looking at the E. end.

Notice the side tracks which once were used for loading and unloading. Also notice the windows which were remodelled with new glass



Cains Coffee Company Building

Oklahoma City, Oklahoma

View from the W., looking at the W. end of
the lean-to garage.

FEB 4 1982

DEC 2 2 1981



Cains Coffee Company Building

Oklahoma City, Oklahoma

View from the E., looking at the E. end of
the lean-to garage.

FEB 4 1982

DEC 22 1981




Cains Coffee Company Building

Oklahoma City, Oklahoma

View of the stairway in the two-story
entryway.

DEC 22 1981 FEB 4 1982



Cains Coffee Company Building

Oklahoma City, Oklahoma

View of the partitions on the remodelled
first level.

FEB 4 1982


DEC 22 1981



Cains Coffee Company Building
Oklahoma City, Oklahoma
View of a typical upper floor

FEB 4 1982

DEC 22 1981



Cains Coffee Company Building

Oklahoma City, Oklahoma

View of the glazed tile on the S. side.

FEB 4 1982

DEC 22 1981



Cains Coffee Company Building

Oklahoma City, Oklahoma

View of the rubble on the third floor.

DEC 22 1981

FEB 4 1982